

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 5590A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAIL LAMP LH	CRACKED	194.22	194.22
1	TAIL LAMP RH	CRACKED	194.22	194.22
1	REAR NUMBER PLATE LIGHT	NOT NECESSARY	79.85	-
1	REAR EXHAUST PIPE	TO REPAIR SEE LABOUR	576.70	-
	LESS 10% DISCOUNT		-104.50	-
	LESS 25% DISCOUNT		-	-97.11
			940.49	291.33
1	REAR CHASSIS FRAME CROSS MEMBER (SN)	BENT	600.00	300.00
	LESS 10% DISCOUNT		-60.00	-
			540.00	300.00
	SPECIAL NETT ITEMS			
1	BACK DOOR LOWER FRAME (SN)	TO REPAIR SEE LABOUR	500.00	-
2	BACK DOOR LOWER HANDLE BAR @\$150.00 (SN)	TO REPAIR SEE LABOUR	300.00	-
2	BACK DOOR LOCK CATCH @\$50.00 (SN)	NOT NECESSARY	100.00	-
2	TAIL LAMP BRACKET @\$50.00 (SN)	NOT NECESSARY	100.00	-
1	REAR NO. PLATE (SN)	BENT	35.00	20.00
1	REAR NO. PLATE BRACKET (SN)	NOT NECESSARY	50.00	-
1	PAN PAC METAL PLATE (SN)	NOT NECESSARY	50.00	-
1	70KM/H STICKER (SN)	NECESSARY	20.00	10.00
			1,155.00	30.00
	<u>LABOUR</u>			
	TO PANEL BEAT & ALIGN REAR PORTION, REMOVE & REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR EXHAUST PIPE, BACK DOOR LOWER FRAME AND BACK DOOR LOWER HANDLE BAR.		1,000.00	500.00
	TO APPLY ANTI RUST COAT AND TUFF KOTE REPAIRED AREAS.	NOT NECESSARY	100.00	-
	TO CHECK AND RECTIFY LIGHTING & WIRING.		50.00	20.00

Report Ref No. CS/SMO21004953/Uvf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	TO SPRAY PAINTING FOR REAR PORTIONS & AFFECTED AREAS.		1,000.00	500.00
	TO REMOVE,REFIT & ALIGN EXHAUST MUFFLER.		150.00	60.00
			2,300.00	1,080.00
	GRAND TOTAL		4,935.49	1,701.33

RECOMMENDED COST OF LUMP SUM REPAIRS		1,350.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/SMO21004953/Uvf3n2

CHUA KANG SENG

Licensed Appraiser