

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/TMI21004961/T1VF3E2

**Date:** 01/06/2021

### REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MR006315		
<b>Claimant Vehicle No :</b>	SHD3328U	<b>Insured Vehicle No :</b>	SKL5286R		
Date of Loss:	19/04/2021	Nature of Claim:	TP	Claim No:	M2101913

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD3328U	Engine No:	D4FDFU580794
Make & Model:	HYUNDAI I40, 1.7 D CRDi (A)	Chassis No:	KMHLB41UMGU091935
Reg. Date:	21/07/2016 (Man. Year: 2016)	Odometer:	776276 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,946.52	75.00	2,871.52	97.45
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,520.00	950.00	570.00	37.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,477.52</b>	<b>1,036.00</b>	<b>3,441.52</b>	<b>76.86</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>313.43</b>	<b>72.52</b>	<b>240.91</b>	<b>76.86</b>
<b>Nett Amount (S\$)</b>	<b>4,790.95</b>	<b>1,108.52</b>	<b>3,682.43</b>	<b>76.86</b>

### INSPECTION

Date of Assignment:	20/04/2021	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	20/04/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Jun 2021)
Parts:	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD3328U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*DOOR SIDE MIRROR LH	Repair	670.00 FL	-	*- FL
2	1		*FRONT DOOR LH	Repair	2,256.40 FL	-	*- FL
3	1		*FRONT FENDER LH	Repair	663.00 FL	-	*- FL
4	1		*FRONT DOOR COMFORTDELGRO LOGO LH	Cut	75.00 F	-	*75.00 F
F=Franchise part. L=ListItemDisc.							
					Sub Total (\$\$)	3,664.40	75.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	717.88	0.00
					Total Parts (\$\$)	2,946.52	75.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	700.00	350.00
2	SPRAY PAINTING CHARGE	New	700.00	600.00
3	TRANSFER OF DOOR	New	120.00	0.00
Gross Labour Cost (\$\$)			1,520.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >