

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8708D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER COVER	DEFORMED	1,106.00	1,106.00
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER BRACKET RH	NOT NECESSARY	35.60	-
1	BOOTLID	TO REPAIR SEE LABOUR	2,174.90	-
1	BOOTLID LAMP RH	CUT	622.20	622.20
1	TAIL LAMP RH	CRACKED	697.80	697.80
1	REAR FENDER RH	TO REPAIR SEE LABOUR	2,171.40	-
1	BOOTLID I40 EMBLEM	NECESSARY	67.90	67.90
1	BOOTLID CRDI EMBLEM	NECESSARY	52.40	52.40
1	BOOTLID H EMBLEM	NECESSARY	63.10	63.10
	LESS 20% DISCOUNT		-1,402.66	
			5,610.64	2,105.12
	NETT ITEMS			
1	BOOTLID CTPL LOGO STICKER (N)	NECESSARY	30.00	30.00
1	BOOTLID CTPL TEL NO STICKER (N)	NECESSARY	30.00	30.00
	LESS 10% DISCOUNT		-	-6.00
			60.00	54.00
	<u>LABOUR</u>			
	WIRING CHARGE.		60.00	30.00
	TUFF KOTE.	NOT NECESSARY	60.00	-
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF BOOTLID AND REAR FENDER RH.		800.00	420.00
	SPRAY PAINTING CHARGE.		750.00	500.00
	REMOVE/REFIX REVERSE SENSOR.		60.00	30.00
			1,730.00	980.00
	GRAND TOTAL		7,400.64	3,139.12

Report Ref No. NS/INC21004978/T1vcn2





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,500.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC21004978/T1vcn2

**MOHAMAD TAUFIKH** 

M.MATAI, AMSAE-A

**Automotive Assessor** 

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser**