



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 2359K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR PANEL	TO REPAIR SEE LABOUR	395.10	-
1	REAR LAMP ASSY,RH	MTG CRACKED	295.00	295.00
1	REAR LAMP LOWER BRACKET RH	DISTORTED	50.30	50.30
1	REAR BUMPER ASSY	BUCKLED	803.00	780.00
1	REAR BUMPER REFLECTOR	CRACKED	76.50	76.50
1	REAR BUMPER SIDE RETAINER	DISTORTED	69.00	69.00
	LESS 25% DISCOUNT		-422.23	-317.70
			1,266.67	953.10
1	REAR EXHAUST PIPE ASSY (LOCAL REPAIR)(SN)	DENTED	1,050.00	280.00
	LESS 25% DISCOUNT		-262.50	-
			787.50	280.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR REVERSE SENSOR (SN)	SHORTED	220.00	200.00
			220.00	200.00
	<b><u>LABOUR</u></b>			
	REMOVE EXHAUST PIPE & REFIT.		100.00	60.00
	WIRINGS.		60.00	20.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR PANEL.		1,000.00	540.00
	SPRAY PAINTING.		1,000.00	450.00
	RUSTPROOFING.	NOT NECESSARY	180.00	-
			2,340.00	1,070.00
	<b>GRAND TOTAL</b>		<b>4,614.17</b>	<b>2,503.10</b>

Report Ref No. CS/SMO21004988/Kvf3n2



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,000.00</b>
---	--	--	-----------------

Report Ref No. CS/SMO21004988/Kvf3n2

**KONG SENG CHEONG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**