

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	SOMPO INSURAN	CE SINGAPORE PL		Ref:	CS/SMO21004988/Kvf3n2	
	50 RAFFLES PLAC SINGAPORE LAND	CE #03-03 O TOWERSINGAPORE 048623		Date:	29/04/2021	
				Code:	SMO	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SKF 7937P	Veh. Inspected	k	SH 2359K	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD2101250/RUC	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign Date		21/04/2021	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA AXIO (A)	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	NKE1657145641	Colour		YELLOW / BLACK	
	Odometer	378111 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	185/60 R15	BRIDGESTONE		9 mm	
	L/H Front Tyre	185/60 R15	BRIDGESTONE		9 mm	
	R/H Rear Tyre	185/60 R15	TOYO		7 mm	
	L/H Rear Tyre	185/60 R15	TOYO		7 mm	
4.	4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	17/04/2021	Inspection Dat	te	21/04/2021	
	Survey held at	CHOON HOCK MOTOR TRADIN	IG CO			
		BLK 176 SIN MING DRIVE				
		#05-03 SIN MING AUTOCARE SINGAPORE 575721				
5a.		Remarks				
		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.		Estimate Days of Repair				
	ESTIMATED NORM	STIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				
	•					