

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21004996/KUF3N2**Date:** 11/11/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00018892100
Claimant Vehicle No :	SKW1441C	Insured Vehicle No :	GBE8850K
Date of Loss:	19/04/2021	Nature of Claim:	TP
		Claim No:	SNM21D202260/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW1441C	Engine No:	1ZRY209242
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Chassis No:	MR053REH104538823
Reg. Date:	29/09/2015 (Man. Year: 2015)	Odometer:	98194 km
Colour:	Metallic Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,173.00	4,773.00	400.00	7.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,270.00	2,890.00	380.00	11.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,443.00	7,663.00	780.00	9.24
Approved Total (Overridden) (S\$)		5,650.00		
(S\$)	8,443.00	5,650.00	2,793.00	33.08
+ GST 7.00/7.00% (S\$)	591.01	395.50	195.51	33.08
Nett Amount (S\$)	9,034.01	6,045.50	2,988.51	33.08

INSPECTION

Date of Assignment:	21/04/2021	Present Location:	Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected:	21/04/2021	Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	10.0 days		

Adjuster: KENNETH KONG**Manager:** Tan Hui Zhen*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Nov 2021)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKW1441C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC REAR BUMPER	Buckled	200.00 F	*200.00 F
2	1		*1 PC REAR BUMPER SIDE RETAINER	Distorted	43.00 F	*43.00 F
3	1		*6 PCS REAR BUMPER CLIPS @2/PC	Necessary	12.00 F	*12.00 F
4	1		*1 PC REAR BOOT	Bent	320.00 F	*320.00 F
5	1		*1 PC REAR BOOT LOGO	Necessary	25.00 F	*25.00 F
6	1		*1 PC REAR BOOT EMBLEM (COROLLA)	Necessary	30.00 F	*30.00 F
7	1		*1 PC REAR BOOT EMBLEM (ALTIS)	Necessary	35.00 F	*35.00 F
8	1		*1 PC REAR BOOT INNER LOCK	Dented	175.00 F	*175.00 F
9	1		*1 PC REAR BOOT INNER RUBBER	Cut	70.00 F	*70.00 F
10	1		*2 PCS REAR BOOT RELFLECTORS @130/PC	Cracked	260.00 F	*260.00 F
11	1		*2 PCS REAR BOOT HINGES @45/PC	Repair	90.00 F	*- F
12	1		*1 PC REAR BOOT OUTER CHROME MOULDING	Warped	155.00 F	*155.00 F
13	1		*1 PC REAR BOOT NUMBER PLATE LAMP	Mtg Cracked	60.00 F	*60.00 F
14	1		*1 PC REAR BOOT OPEN SENSOR	Dented	85.00 F	*85.00 F
15	1		*2 PCS TAILLAMPS @160/PC	Dented/Cut	320.00 F	*320.00 F
16	1		*1 PC REAR CENTRE PANEL	Bent	220.00 F	*220.00 F
17	1		*1 PC FRT BUMPER	Buckled	195.00 F	*195.00 F
18	1		*1 PC FRT BUMPER REINFORCEMENT	Repair	120.00 F	*- F
19	1		*1 PC FRT BUMPER SPONGE	Serviceable	50.00 F	*- F
20	1		*6 PCS FRT BUMPER CLIPS @2/PC	Necessary	12.00 F	*12.00 F
21	1		*1 PC FRT GRILLE	Dented	150.00 F	*150.00 F
22	1		*4 PCS FRT GRILLE CLIPS @2/PC	Necessary	8.00 F	*8.00 F
23	1		*2 PCS HEADLAMPS @650/PC	Mtg Cracked	1,300.00 F	*1,300.00 F
24	1		*2 PCS HEADLAMP TOP CHROME @70/PC	Serviceable	140.00 F	*- F
25	1		*1 PC BONNET	Bent	295.00 F	*295.00 F
26	1		*1 PC BONNET INNER LOCK	Distorted	60.00 F	*60.00 F
27	1		*1 PC FRT SUPPORT PANEL	Bent	200.00 F	*200.00 F
28	1		*1 PC AIRCON CONDENSER	Punctured	320.00 F	*320.00 F
29	1		*1 PC FRT BRACE PANEL	Distorted	45.00 F	*45.00 F
Supplementary #1						
30	1		*1 PC REAR BUMPER REINFORCEMENT	Bent	140.00 F	*140.00 F
31	1		*1 PC LH TAILLAMP LOWER RETAINER	Cracked	38.00 F	*38.00 F

F=Franchise part.

Total Parts (S\$) **5,173.00** **4,773.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	60.00	60.00
2	REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, REAR BOTH ATTACHMENT, LOCK ASSY, CUT, WELD & RENEW REAR PANEL, KNOCK & REPAIR REAR BOTH FENDERS & REALIGN THE SAME	New	800.00	700.00
3	PUTTY & RESPRAY ON REAR BOTH FENDERS, REAR BOOT, REAR PANEL, REAR BUMPER & REAR AFFECTED AREAS	New	800.00	720.00
4	REMOVE & REFIX AIRCON, CHECK, VACUUM & REFILL GAS	New	100.00	100.00
5	REMOVE & REFIX FRT BUMPER ASSY, HEADLAMPS, GRILLE, BONNET & ATTACHMENT, RADIATOR & MOTOR, FRT FENDERS, CUT, WELD & RENEW FRT SUPPORT PANEL, KNOCK & REPAIR FRT FENDERS & REALIGN THE SAME	New	700.00	600.00
6	PUTTY & RESPRAY ON FRT BUMPER, REINFORCEMENT, SUPPORT PANEL, BONNET, FRT FENDERS & FRT AFFECTED AREAS	New	700.00	600.00
7	REMOVE & REFIX REVERSE SENSOR, REVERSE CAMERA & RESET SYSTEM	New	50.00	50.00
8	RUSTPROOFING	New	60.00	60.00
Gross Labour Cost (\$\$)			3,270.00	2,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >