

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/III21005001/APA3Q2**Date:** 02/08/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D18MCV0001978_02
<b>Claimant Vehicle No :</b>	GBL805H	<b>Insured Vehicle No :</b>	GBB2280K
Date of Loss:	19/04/2021	Nature of Claim:	TP
		Claim No:	MCV2021D0001755

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBL805H</b>		
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5 DR (M)	Engine No:	1KDB070991
Reg. Date:	17/03/2021 (Man. Year: 2020)	Chassis No:	JTFHT02P700251545
Colour:	Silver	Odometer:	909 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	18,696.85	5,555.60	13,141.25	70.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,980.00	2,240.00	3,740.00	62.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>24,676.85</b>	<b>7,795.60</b>	<b>16,881.25</b>	<b>68.41</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,727.38</b>	<b>545.69</b>	<b>1,181.69</b>	<b>68.41</b>

<b>Nett Amount (S\$)</b>	<b>26,404.23</b>	<b>8,341.29</b>	<b>18,062.94</b>	<b>68.41</b>
<b>+ Loss of Use (6.0 x S\$100.00/day) (S\$)</b>		600.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>8,943.29</b>		
<b>Global Sum Settlement (S\$)</b>		<b>8,900.00</b>		

INSPECTION

Date of Assignment: 21/04/2021

Date Inspected: 21/04/2021

Estimated Period of Repair: 6.0 days

Inspected At:

New Hock Teck Motor Pte Ltd (HQ)  
1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit  
Singapore 417883

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 21 Jun 2021)
<b>Parts:</b> 213	TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for GBL805H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented	1,712.45 F	*1,712.45 FL
2	2		*REAR BOOT LID HINGE	Not Necessary	343.40 F	*- FL
3	1		*REAR BOOT LID TOYOTA HIACE STICKER	Necessary	57.60 F	*57.60 FL
4	1		*REAR BOOT LID EMBLEM LOGO	Necessary	41.10 F	*41.10 FL
5	1		*REAR BOOT LID CENTRE MOULDING	Deformed	281.90 F	*281.90 FL
6	1		*REAR BOOT LID INNER LOCK	Jammed	374.25 F	*374.25 FL
7	1		*REAR BOOT LID INNER RUBBER	Cut	381.90 F	*381.90 FL
8	1		*REAR BOOT LID INNER TRIM BOARD	Torn	581.10 F	*165.00 FL
9	10		*REAR BOOT LID INNER TRIM BOARD CLIP	Necessary	65.00 F	*30.00 FL
10	1		*REAR BOOT LID WINDSCREEN SEAL	Necessary	105.00 F	*105.00 FL
11	2		*REAR TAIL LAMP	Cut	748.90 F	*748.90 FL
12	2		*REAR TAIL LAMP PANEL	Repair	743.70 F	*- FL
13	2		*REAR TAIL LAMP LOWER COVER	Repair	364.20 F	*- FL
14	2		*REAR TAIL LAMP LOWER COVER RETAINER	Not Necessary	342.90 F	*- FL
15	1		*REAR BUMPER	Deformed	374.45 F	*374.45 FL
16	8		*REAR BUMPER CLIP	Necessary	52.00 F	*30.00 FL
17	2		*REAR BUMPER SIDE RETAINER	Necessary	262.70 F	*262.70 FL
18	1		*REAR END PANEL OUTER	Dented	581.10 F	*581.10 FL
19	1		*REAR END PANEL INNER	Repair	591.25 F	*- FL
20	8		*REAR END PANEL TOP CLIP	Not Necessary	52.00 F	*- FL
21	1		*REAR FLOOR PANEL	Repair	1,972.45 F	*- FL
22	1		*REAR FLOOR PANEL TOP MOULDING	Bent	274.45 F	*274.45 FL
23	8		*REAR FLOOR PANEL TOP MOULDING CLIP	Necessary	52.00 F	*10.00 FL
24	1		*REAR SPARE TYRE BRACKET	Not Necessary	172.10 F	*- FL
25	1		*REAR EXHAUST	Not Necessary	1,712.85 F	*- FL
26	1		*REAR CENTRE EXHAUST	Not Necessary	1,829.10 F	*- FL
27	1		*REAR BOOT LID WINDSCREEN SEAL	Repeated	105.00 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*REAR BOOT LID 70KM/H STICKER	Necessary	20.00 FS	*10.00 FS
29	1		*REAR BOOT LID NUMBER PLATE	Bent	50.00 FS	*30.00 FS
30	1		*REAR BOOT LID CAMERA	Damaged	680.00 FS	*380.00 FS
31	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
32	1		*REAR FLOOR PANEL PLYWOOD	Not Necessary	650.00 FS	*- FS
33	1		*REAR FLOOR PANEL CARPET	Not Necessary	850.00 FS	*- FS
34	1		*REAR WINDSCREEN GLASS	Cut	1,298.00 F	*1,150.00 FL
35	1		*REAR WINDSCREEN GLASS SHOCK ABSORBER	Not Necessary	624.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>18,696.85</b>	<b>7,200.80</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$)</b>	0.00	1,645.20
<b>Total Parts (\$)</b>	<b>18,696.85</b>	<b>5,555.60</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REFIT REAR RACK COMPARTMENT	New	800.00	0.00
2	TO REMOVE & REFIT CUSHION ,PLYWOOD & CARPET	New	380.00	250.00
3	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
4	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
5	GUM	New	50.00	50.00
6	TO REMOVE & REFIT REAR & CENTRE EXHAUST	New	380.00	0.00
7	TO CHECK WIRING	New	100.00	30.00
8	TUFF KOTE	New	150.00	60.00
9	PANEL BEATING	New	1,800.00	800.00
10	SPRAY PAINTING	New	1,600.00	800.00
11	LABOUR FOR REMOVE & TRANSFER ALL REAR TAILGATE FITTING	New	200.00	80.00
12	LABOT FOR REPAIR & STRAIGHTEN BOTH REAR CHASSIS FRAME	New	300.00	0.00
			<b>Gross Labour Cost (S\$)</b>	<b>5,980.00</b>
				<b>2,240.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >