

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21005003/TGA3Q2**Date:** 18/07/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070103751
Claimant Vehicle No :	SMP192R	Insured Vehicle No :	SLN8240E
Date of Loss:	19/04/2021	Nature of Claim:	TP
		Claim No:	8459782750SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP192R	Engine No:	S530435794
Make & Model:	MAZDA AXELA, 1.5 (A)	Chassis No:	BMLFP101413
Reg. Date:	05/09/2019 (Man. Year: 2019)	Odometer:	93345 km
Colour:	Blue		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,677.84	3,521.70	2,156.14	37.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,650.00	1,320.00	5,330.00	80.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,327.84	4,841.70	7,486.14	60.73
Approved Total (Overridden) (S\$)		3,800.00		
(S\$)	12,327.84	3,800.00	8,527.84	69.18
+ GST 7.00/7.00% (S\$)	862.95	266.00	596.95	69.18
Nett Amount (S\$)	13,190.79	4,066.00	9,124.79	69.18
+ Car Rental (6.0 x S\$100.00/day + 7.00% GST) (S\$)		642.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,715.45		
Global Sum Settlement (S\$)		4,700.00		

INSPECTION

Date of Assignment:	21/04/2021		
Date Inspected:	23/04/2021	Inspected At:	AP Automotive Services Pte Ltd (HQ) Blk 9006 Tampines Street 93, #01-202 Singapore 528840
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	1,026.00 FL	*1,026.00 FL
2	1		*BOOTLID LOGO -MAZDA	Necessary	79.50 FL	*79.50 FL
3	1		*BOOTLID EMBLEM -AXELA	Necessary	59.00 FL	*59.00 FL
4	1		*BOOTLID EMBLEM -SKYACTIV	Necessary	68.00 FL	*68.00 FL
5	1		*BOOTLID LAMP RH (NPA)	Not Necessary	0.00 FL	*- FL
6	1		*BOOTLID LOCK	Not Necessary	291.80 FL	*- FL
7	1		*BOOTLID LOCK CATCH	Not Necessary	74.00 FL	*- FL
8	1		*BOOTLID WEATHERSTRIP	Cut	114.00 FL	*114.00 FL
9	1		*TAIL LAMP RH	Cracked	567.00 FL	*567.00 FL
10	1		*REAR BUMPER	Deformed	1,298.00 FL	*1,298.00 FL
11	4		*SET REAR BUMPER REVERSE SENSOR (NPA)	Not Necessary	0.00 FL	*- FL
12	1		*REAR BUMPER REFLECTOR RH	Cracked	67.50 FL	*67.50 FL
13	1		*REAR BUMPER RETAINER RH	Cracked	78.80 FL	*78.80 FL
14	1		*REAR BUMPER REINFORCEMENT BAR	Bent	438.00 FL	*438.00 FL
15	1		*REAR BUMPER SPONGE	Not Necessary	137.80 FL	*- FL
16	1		*REAR BUMPER UNDERCOVER	Not Necessary	293.65 FL	*- FL
17	1		*REAR FENDER INNER TRIM RH	Not Necessary	271.55 FL	*- FL
18	1		*REAR FENDER COWLING RH	Not Necessary	152.90 FL	*- FL
19	1		*END PANEL	Bent	560.00 FL	*560.00 FL
20	1		*END PANEL TOP GARNISH	Deformed	219.80 FL	*219.80 FL
21	1		*REAR SMART LOCK ANTENNA	Not Necessary	197.30 FL	*- FL
22	1		*SPARE WHEEL PANEL (NPA)	Repair	0.00 FL	*- FL
23	1		*SPARE WHEEL PANEL TOP BOARD (NPA)	Not Necessary	0.00 FL	*- FL
24	1		*SPARE WHEEL PANEL ACCESSORIES SPONGE	Not Necessary	102.70 FL	*- FL
25	1		*EXHAUST PIPE (NPA)	Not Necessary	0.00 FL	*- FL
26	1		*EXHAUST HEAT SHIELD (NPA)	Not Necessary	0.00 FL	*- FL
27	2		*SET EXHAUST MOUNTING (NPA)	Not Necessary	0.00 FL	*- FL
28	1		*REAR NUMBER PLATE	Not Necessary	100.00 FS	*- FS
29	1		*TAIL LAMP CLIPS	Necessary	50.00 FS	*10.00 FS
30	1		*REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
31	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	100.00 FS	*- FS
32	1		*REAR FENDER COWLING CLIPS	Not Necessary	100.00 FS	*- FS
33	1		*END PANEL SEALANT	Necessary	250.00 FS	*40.00 FS
34	1		*END PANEL TOP GARNISH CLIPS	Necessary	100.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,897.30	4,665.60
- List Item Discount on L Items 20.00/25.00% (\$\$)	1,219.46	1,143.90
Total Parts (\$\$)	5,677.84	3,521.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	2,000.00	600.00
2	SPRAY PAINT ON AFFECTED AREAS	New	1,800.00	600.00
3	TO RNR REAR EXHAUST	New	350.00	0.00
4	TO CHECK WIRING AND TAIL LAMP FUNCTION }	New	150.00	30.00
5	TO CHECK WIRING AND BOOTLID LAMP FUNCTION }	New	150.00	0.00
6	TO RNR REAR INNER TRIM AND UPHOLSTERY	New	400.00	60.00
7	TO CHECK WATER LEAK	New	150.00	0.00
8	TO RNR FUEL TANK	New	250.00	0.00
9	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	0.00
10	TO RNR REAR BOOT MECHANISM	New	350.00	0.00
11	TO RNR REAR REVERSE SENSPR AND CHECK FUNCTION	New	150.00	30.00
12	TO PERFORM RUST PROOFING	New	300.00	0.00
Gross Labour Cost (\$)			6,650.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >