



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBP 9390G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HEAD LAMP	SERVICEABLE	150.00	-
1	FRONT TYRE	SERVICEABLE	150.00	-
1	FRONT WHEEL RIM	SERVICEABLE	280.00	-
1	HEAD LAMP BRACKET	TO REPAIR SEE LABOUR	25.00	-
1	FRONT COWLING LOGO	NOT NECESSARY	18.00	-
1	SPEEDOMETER	SERVICEABLE	315.00	-
1	FRONT BRAKE DISC	SERVICEABLE	85.00	-
1	FRONT BRAKE CALIPER	SERVICEABLE	265.00	-
1	ERP UNIT	SERVICEABLE	160.00	-
1	SIDE FAIRING LOGO	NECESSARY	18.00	18.00
1	FRONT SIGNAL LAMP LH	SERVICEABLE	35.00	-
1	FRONT SIGNAL LAMP RH	SERVICEABLE	35.00	-
1	CLUTCH LEVER	TO REPAIR SEE LABOUR	28.00	-
1	SET BALANCER	DENTED	50.00	50.00
1	HANDLE BAR	SERVICEABLE	85.00	-
1	SET MIRROR	SERVICEABLE	60.00	-
2	FRONT FOOT REST @\$28.00	CUT (1PC ONLY)	56.00	28.00
2	REAR FOOT REST @\$28.00	SERVICEABLE	56.00	-
1	GEAR PEDAL	SERVICEABLE	38.00	-
1	MAIN STAND	TO REPAIR SEE LABOUR	45.00	-
1	SWING ARM	SERVICEABLE	295.00	-
1	SWING ARM SHAFT	SERVICEABLE	35.00	-
1	FRONT FORK ASSY LH	SERVICEABLE	140.00	-
1	FRONT FORK ASSY RH	SERVICEABLE	140.00	-
1	FRONT FORK BRACKET	SERVICEABLE	80.00	-
1	REAR WHEEL FENDER	SERVICEABLE	75.00	-
1	REAR EXHAUST / MUFFLER	TO REPAIR SEE LABOUR	320.00	-

Report Ref No. CS/AGI21005005/Kvf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-303.90	-9.60
			2,735.10	86.40
1	HEAD LAMP COWLING (SN) }	DENTED / CUT	75.00	300.00
1	HEAD LAMP GARNISH (SN) }	CRACKED	95.00	-
1	FRONT WHEEL FENDER (SN) }	CUT	65.00	-
1	FRONT COWLING (SN) }	CRACKED	70.00	-
1	SIDE FAIRING - LH (SN) }		145.00	-
1	SIDE FAIRING - RH (SN) }		145.00	-
1	ENGINE SIDE COVER (SN) }	DENTED / SCRATCHED	185.00	-
	LESS 10% DISCOUNT		-78.00	-
			702.00	300.00
	<u>SPECIAL NETT ITEMS</u>			
1	BOX CARRIER (SN)	DENTED / CUT	120.00	120.00
1	TOP BOX (SN)	SERVICEABLE	200.00	-
1	REAR LICENCE PLATE (SN)	BENT	20.00	12.00
1	FORK OIL (SN)	NOT NECESSARY	20.00	-
4	FORK SEAL @\$10.00 (SN)	NOT NECESSARY	40.00	-
1	SET STICKER (SN)	NECESSARY	120.00	50.00
			520.00	182.00
	<u>LABOUR</u>			
	TOWING SERVICE.		50.00	30.00
	TO REALIGN REAR WHEEL SWING ARM AND CHASSIS.	NOT NECESSARY	100.00	-
	TO CHECK WIRING SYSTEM.		30.00	10.00
	TO REMOVE AND REFIX REAR BOX AND BRACKET.	NOT NECESSARY	40.00	-
	TO DISMANTLE / RENEW ACCIDENT DAMAGED PORTION. TO PANEL BEAT, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF HEAD LAMP BRACKET, CLUTCH LEVER, MAIN STAND AND REAR EXHAUST / MUFFLER.		400.00	120.00

Report Ref No. CS/AGI21005005/Kvf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA / PANEL.	NOT NECESSARY	300.00	-
			920.00	160.00
GRAND TOTAL			4,877.10	728.40
RECOMMENDED COST OF REPAIRS				728.40

Report Ref No. CS/AGI21005005/Kvf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.