8/27/2021 Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/GRB21005014/ABS3Q2

Date:

27/08/2021

REFERENCE

Date of Loss:

Handling Insurer: India International Insurance Pte Ltd Policy No:

D21MFL0000447

Claimant Vehicle No:

SMV178B 13/04/2021 Insured Vehicle No: Nature of Claim:

SLR8294D TP

Claim No: MFL2021D0001720

CDN181484

101852 km

WAUZZZ8F8BN013916

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **SMV178B** 

Make & Model: AUDI A5, 2.0 TFSI QUATTRO (A)

30/06/2011 (Man. Year: 2011) Reg. Date:

Colour: White

**Engine Capacity:** 1984 cc Market Value/New Car Price: N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes

Footbrake (Serviceable):

Engine No:

Chassis No:

Odometer:

Yes

Handbrake (Serviceable):

Yes

**Engine Modification:** 

No

Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 245/45 R17 Rear Tyre Size: Rear Left Side:

245/45 R17 Goodyear 6 mm

Front Left Side: Goodyear 6 mm Front Right Side: Goodyear 6 mm

Rear Right Side:

Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		9,918.00	6,001.20	3,916.80	39.49
Miscellaneous Items		0.00	0.00	0.00	
Labour		4,420.00	1,460.00	2,960.00	66.97
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	14,338.00	7,461.20	6,876.80	47.96
	Approved Total (Overridden) (S\$)		5,900.00		

**Nett Amount (S\$)** 14,338.00 5,900.00 8,438.00 58.85

> Global Sum Settlement (S\$) 0.00

INSPECTION

Date of Assignment: 21/04/2021

Ever Sen Auto Service (HQ) Date Inspected: 21/04/2021 Inspected At: Blk 3022A, Ubi Road 1, #01-49

Estimated Period of Repair: 6.0 days

Singapore 408716

Adjuster: **ADRIAN LING** Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### **REPAIR DETAILS**

Reference

Part Source: (Last Synchronised: 27 Aug 2021)

AUDI A5 2.0 TFSI QUATTRO (A) (Model not available in database) Parts: N/A

(Price-denominated Standard List) Labour: Repairer's

(Unsubmitted, no print-code for SMV178B) **Print Code:** 

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*BUMPER -REAR	Distorted	2,513.00 F	*2,513.00 FN
2	3	*REVERSING SENSOR	Not Necessary	1,005.00 F	*- FN
3	1	*BUMPER RETAINER	N/S Damaged	210.00 F	*105.00 FN
4	1	*BUMPER REINFORCEMENT -REAR	Not Necessary	460.00 F	*- FN
5	1	*FENDER -REAR LH	Distorted	2,520.00 F	*2,520.00 FN
6	1	*SPLASH SHIELD	Torn	135.00 F	*135.00 FN
7	1	*WHEEL RIM	Cut	1,015.00 F	*1,015.00 FN
8	1	*TYRE	Not Necessary	475.00 F	*- FN
9	1	*WHEEL HUB BEARING -REAR	Not Necessary	850.00 F	*- FN
10	1	*TRAILING ARM L/H & R/H	Not Necessary	355.00 F	*- FN
11	1	*TAIL LAMP -LH	Cracked	380.00 F	*380.00 FN
F=Fr	anchise part. N=NettItemD	Disc.			
			Sub Total (S\$)	9,918.00	6,668.00
			- Nett Item Discount on N Items 0.00/10.00% (S\$)	0.00	666.80
			Total Parts (S\$)	9,918.00	6,001.20

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No P	Particulars	Lab.Type	Repairer's	Amount
Labour	ur Items			
1 <b>A</b>	ACCIDENT REPAIR PANEL BEATING	New	2,800.00	800.00
2 <b>R</b>	RESPRAY PAINT WORK ON REPAIR AREA	New	1,000.00	500.00
3 <b>C</b>	CONDUCT WHEEL ALIGNMENT	New	120.00	80.00
4 <b>U</b>	JC.UNDER CARRIAGE REPAIR & REPLACE	New	300.00	0.00
5 <b>R</b>	RUSTPROOFING TREATMENT	New	200.00	80.00
		Gross Labour Cost (S\$)	4,420.00	1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >