

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21005015/TGA3Q2**Date:** 10/08/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SMX3534B**Insured Vehicle No :** SMY1271S

Date of Loss: 18/04/2021

Nature of Claim: TP

Claim No: 8678218726SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMX3534B**

Make & Model: HONDA SHUTTLE, 1.5 (A)

Engine No: L15B6020255

Reg. Date: 07/01/2021 (Man. Year: 2019)

Chassis No: GK82100200

Colour: Black

Odometer: 10894 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,553.55	7,782.39	6,771.16	46.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,500.00	3,360.00	5,140.00	60.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,053.55	11,142.39	11,911.16	51.67
Approved Total (Overridden) (S\$)		9,000.00		
(S\$)	23,053.55	9,000.00	14,053.55	60.96
+ GST 7.00/7.00% (S\$)	1,613.75	630.00	983.75	60.96
Nett Amount (S\$)	24,667.30	9,630.00	15,037.30	60.96
+ Car Rental (10.0 x S\$100.00/day + 7.00% GST) (S\$)		1,070.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		60.00		
Nett Liability (S\$)		10,767.45		

INSPECTION

Date of Assignment: 21/04/2021

Date Inspected: 23/04/2021 Inspected At:

AP Automotive Services Pte Ltd (HQ)
Blk 9006 Tampines Street 93, #01-202
Singapore 528840

Estimated Period of Repair: 8.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	862.00 FL	*862.00 FL
2	1		*TAILGATE WINDSCREEN MOULDING	Necessary	126.75 FL	*126.75 FL
3	1		*TAILGATE LAMP L+R	N/S Cut / O/S Not Necessary	904.00 FL	*452.00 FL
4	1		*TAILGATE OUTER GARNISH	Cracked	347.70 FL	*347.70 FL
5	1		*TAILGATE CHROME	Not Necessary	385.65 FL	*- FL
6	1		*TAILGATE LOGO -HONDA	Necessary	79.20 FL	*79.20 FL
7	1		*TAILGATE HANDLE SWITCH	Not Necessary	267.90 FL	*- FL
8	2		*TAILGATE NUMBER PLATE LAMP L+R	Not Necessary	170.60 FL	*- FL
9	1		*TAILGATE LOCK (NPA)	Not Necessary	0.00 FL	*- FL
10	1		*TAILGATE LOCK CATCH	Not Necessary	75.50 FL	*- FL
11	1		*TAILGATE INNER TRIM	Buckled	237.81 FL	*237.81 FL
12	1		*TAILGATE INNER HANDLE	Not Necessary	45.80 FL	*- FL
13	2		*SET TAILGATE HINGE	Not Necessary	190.40 FL	*- FL
14	2		*SET TAILGATE DAMPER	Not Necessary	359.70 FL	*- FL
15	1		*TAILGATE WEATHERSTRIP	Twisted	149.70 FL	*149.70 FL
16	1		*TAIL LAMP L+R	N/S Cracked / O/S NotNecessary	1,197.00 FL	*598.50 FL
17	1		*TAIL LAMP PANEL L+R	N/S Bent / O/S Not Necessary	428.50 FL	*214.25 FL
18	1		*REAR BUMPER	Torn	1,209.00 FL	*1,209.00 FL
19	1		*REAR BUMPER CHROME	Cut	121.00 FL	*121.00 FL
20	1		*REAR BUMPER REFLECTOR L+R	N/S Missing / O/S NotNecessary	141.20 FL	*70.60 FL
21	2		*SET REAR BUMPER REVERSE SENSOR	Necessary	344.90 FL	*344.90 FL
22	1		*REAR BUMPER TOW COVER	Not Necessary	85.90 FL	*- FL
23	1		*REAR BUMPER RETAINER L+R	N/SDeformed/O/S Not Necessary	160.40 FL	*80.20 FL
24	1		*REAR BUMPER BRACKET	Deformed	105.23 FL	*105.23 FL
25	1		*REAR BUMPER UNDERCOVER	Not Necessary	472.45 FL	*- FL
26	1		*REAR FENDER LH	Bent	909.00 FL	*909.00 FL
27	1		*REAR FENDER INNER PANEL LH	Bent	578.20 FL	*478.00 FL
28	1		*REAR FENDER INNER TRIM TOP LH (NPA)	Not Necessary	0.00 FL	*- FL
29	1		*REAR FENDER INNER TRIM BOTTOM LH	Cracked	351.00 FL	*351.00 FL
30	1		*REAR FENDER COWLING L+R	N/S Torn / O/S Not Necessary	211.80 FL	*105.90 FL
31	1		*REAR WHEELHOUSE LH (NPA)	Repair	0.00 FL	*- FL
32	1		*END PANEL	Bent	455.00 FL	*455.00 FL
33	1		*END PANEL TOP GARNISH	Deformed	134.10 FL	*134.10 FL
34	1		*REAR SMART LOCK ANTENNA	Not Necessary	194.50 FL	*- FL
35	1		*REAR BUZZER	Cracked	145.70 FL	*145.70 FL
36	1		*SPAREWHEEL PANEL	Buckled	900.00 FL	*800.00 FL
37	1		*SPAREWHEEL PANEL TOP BOARD	Deformed	685.50 FL	*420.30 FL
38	1		*SPAREWHEEL PANEL TOOLS SPONGE	Deformed	143.90 FL	*143.90 FL
39	1		*SPAREWHEEL PANEL ACCESSORIES TRAY	Deformed	411.25 FL	*411.25 FL
40	1		*SPAREWHEEL PANEL ACCESSORIES TRAY FRONT COVER	Not Necessary	178.70 FL	*- FL
41	1		*REAR CHASSIS LH (NPA)	Repair	0.00 FL	*- FL
42	1		*REAR FENDER RH (NPA)	Repair	0.00 FL	*- FL
43	1		*TAILGATE WINDSCREEN SEALANT	Necessary	150.00 FS	*60.00 FS
44	1		*TAILGATE INNER TRIM CLIPS	Necessary	100.00 FS	*20.00 FS
45	1		*REVERSE CAMERA	Not Necessary	800.00 FS	*- FS
46	1		*TAIL LAMP CLIPS	Necessary	50.00 FS	*20.00 FS
47	1		*TAIL LAMP PANEL SEALANT	Not Necessary	120.00 FS	*- FS
48	1		*REAR NUMBER PLATE	Not Necessary	120.00 FS	*- FS
49	1		*REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*REAR FENDER SEALANT	Necessary	250.00 FS	*50.00 FS
51	1		*REAR FENDER WINDOW SEALANT	Necessary	200.00 FS	*50.00 FS
52	1		*REAR FENDER INNER PANEL SEALANT	Not Necessary	250.00 FS	*- FS
53	1		*REAR FENDER INNER TRIM CLIPS	Necessary	200.00 FS	*20.00 FS
54	1		*REAR FENDER COWLING CLIPS	Necessary	100.00 FS	*10.00 FS
55	1		*REAR WHEELHOUSE SEALANT	Not Necessary	200.00 FS	*- FS
56	1		*END PANEL SEALANT	Necessary	200.00 FS	*40.00 FS
57	1		*END PANEL TOP GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
58	1		*SPAREWHEEL PANEL SEALANT	Not Necessary	300.00 FS	*- FS
59	1		*REAR CHASSIS SEALANT	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

			Sub Total (\$)	17,306.94	9,652.99
			- List Item Discount on L Items 20.00/20.00% (\$)	2,753.39	1,870.60
			Total Parts (\$)	14,553.55	7,782.39

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	3,000.00	1,600.00
2	SPRAY PAINT ON AFFECTED AREAS	New	1,800.00	1,400.00
3	TO RNR REAR WINDSCREEN	New	350.00	120.00
4	TO RNR REAR EXHAUST	New	250.00	0.00
5	TO CHECK WIRING AND TAILLAMP FUNCTION }	New	150.00	30.00
6	TO CHECK WIRING AND TAILGATE LAMP FUNCTION }	New	150.00	0.00
7	TO RNR REAR INNER TRIM AND UPHOLSTERY	New	400.00	60.00
8	TO CHECK WHEEL ALIGNMENT AND ADJUST	New	250.00	0.00
9	TO RNR UNDERCARRIAGE	New	250.00	0.00
10	TO CHECK WATER LEAK	New	150.00	20.00
11	TO RNR FUEL TANK	New	250.00	0.00
12	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	0.00
13	TO RNR REAR TAILGATE MECHANISM	New	350.00	60.00
14	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	New	150.00	30.00
15	TO PERFORM RUST PROOFING	New	400.00	40.00
Gross Labour Cost (\$\$)			8,500.00	3,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >