

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB21005016/EBS3Q2
Date: 16/08/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SDA8628J	Insured Vehicle No :	SLL3216U
Date of Loss:	14/04/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0001869

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDA8628J		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 L CVT (A)	Engine No:	1ZRX503797
Reg. Date:	04/05/2015 (Man. Year: 2015)	Chassis No:	MR053REH104531443
Colour:	Silver	Odometer:	91854 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,325.15	1,856.65	3,468.50	65.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,510.00	4,300.00	3,210.00	42.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,835.15	6,156.65	6,678.50	52.03
+ GST 7.00/7.00% (S\$)	898.46	430.97	467.49	52.03

Nett Amount (S\$)	13,733.61	6,587.62	7,145.99	52.03
	+ Car Rental (S\$)	900.00		
	+ Doc/Search Fee (S\$)	7.45		
	Nett Liability (S\$)	7,495.07		

INSPECTION

Date of Assignment: 21/04/2021

Date Inspected: 26/04/2021

Estimated Period of Repair: 7.0 days

Inspected At: Borneo Motors (S) Pte Ltd (Ubi)
17 Ubi Road 4
Singapore 408611

Adjuster: CHEN TSUE YEE**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jun 2021)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 L CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDA8628J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	30.00 FS	*30.00 FS
2	1		*COVER ,RR BUMPER	Dented	556.40 FS	*556.40 FS
3	1		*RETAINER ,RR BUMPER L	Not Necessary	60.40 FS	*- FS
4	1		*RETAINER ,RR BUMPER L	Not Necessary	109.30 FS	*- FS
5	1		*RETAINER ,RR BUMPER R	Not Necessary	60.40 FS	*- FS
6	1		*RETAINER ,RR BUMPER R	Not Necessary	109.30 FS	*- FS
7	10		*CLIPS	Necessary	41.00 FS	*41.00 FS
8	1		*REINFORCEMENT RR	Bent	399.50 FS	*399.50 FS
9	1		*ARM ,RR BUMPER ,OUTE	Not Necessary	68.20 FS	*- FS
10	1		*ARM ,RR BUMPER ,OUTE	Not Necessary	68.20 FS	*- FS
11	1		*PANEL ,LAMP LOWER	Dented	670.00 FS	*670.00 FS
12	1		*PLATE ,RR FLOOR	Not Necessary	241.90 FS	*- FS
13	1		*COVER ,SPARE WHEEL	Not Necessary	267.00 FS	*- FS
14	1		*PANEL SUB-ASSY ,LUGG	Not Necessary	793.20 FS	*- FS
15	1		*WEATHERSTRIP ,LUGGAGE	Not Necessary	175.80 FS	*- FS
16	1		*LOCK ASSY ,LUGGAGE C	Not Necessary	399.50 FS	*- FS
17	1		*STRIKER LUGGAGE COM	Not Necessary	15.30 FS	*- FS
18	1		*LUGGAGE COMP EMBLEM	Not Necessary	61.60 FS	*- FS
19	1		*EMBLEM SYMBOL	Not Necessary	41.00 FS	*- FS
20	1		*EMBLEM SYMBOL	Not Necessary	45.60 FS	*- FS
21	1		*LAMP ASSY ,RR COMB LH	Not Necessary	379.80 FS	*- FS
22	1		*LAMP ASSY ,RR COMB RH	Not Necessary	379.80 FS	*- FS
23	1		*ELECTRICAL ANTENNA	Not Necessary	192.20 FS	*- FS
24	1		*BACK SENSOR 1D4 310A	Shorted	159.75 FS	*159.75 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)
5,325.15
1,856.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	DRILL HOLE & INSTALL REAR REVERSE SENSOR	New	180.00	180.00
2	CHECK LIGHTING & CONDUCT WATER LEAK TEST	New	180.00	180.00
3	SUPPLY SEALANT (NETT) -REAR END PANEL	New	60.00	60.00
4	REMOVE & INSTALL REAR COMPARTMENT CARPET GARNISH AND TRIMMING TO ASSIST REPAIR	New	360.00	360.00
5	TO RESET ECU AND REPROGRAMME	New	180.00	180.00
6	REPLACE REAR ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS	New	3,600.00	2,160.00
7	RESPRAY JOB ON REAR ACCIDENT AFFECTED AREAS	New	2,950.00	1,180.00
Gross Labour Cost (S\$)			7,510.00	4,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >