



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBS 317M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	HANDLE BAR (CONSISTENT)	DISTORTED	180.00	180.00
1	SET BALANCER(CONSISTENT)	O/S CUT / N/S NOT NECESSARY	210.00	45.00
1	FRONT RH PANEL (CONSISTENT)	CUT / CRACKED	280.00	280.00
1	FRONT MUDGUARD (CONSISTENT)	CUT	350.00	140.00
1	SET FORK TUBE (CONSISTENT)	DISTORTED / LEAKED	1,200.00	980.00
1	FORK UNDER BRACKET (CONSISTENT)	NOT NECESSARY	550.00	-
1	FRONT RH L PANEL (CONSISTENT)	NOT NECESSARY	250.00	-
1	SET FRONT SIDE L/RH SHROUD (MISSING) (CONSISTENT)	BROKEN / CUT	360.00	360.00
1	RH LOWER FLOOR PANEL (CONSISTENT)	NOT NECESSARY	280.00	-
1	STEP PANEL -FOOT REST RH (CONSISTENT)	CUT / DEFORMED	280.00	280.00
1	RH BODY CENTRE PANEL(CONSISTENT)	TO REPAIR SEE LABOUR	220.00	-
1	REAR RH PANEL (CONSISTENT)	NOT NECESSARY	250.00	-
1	EXHAUST PIPE (CONSISTENT)	DENTED	1,500.00	680.00
1	EXHAUST GUARD CENTRE (CONSISTENT)	CUT	150.00	135.00
1	EXHAUST GUARD FRONT (CONSISTENT)	CUT	190.00	95.00
1	PILLAR FOOT REST RH (CONSISTENT)	NOT NECESSARY	90.00	-
1	LH FRONT SIGNAL (CONSISTENT)	MTG CRACKED	125.00	125.00
	LESS 10% DISCOUNT		-646.50	-330.00
			5,818.50	2,970.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR CARRIER BOX (SN)(CONSISTENT)	CUT / BENT	900.00	300.00
1	YAMAHA EMBLEM (SN)(CONSISTENT)	NOT NECESSARY	130.00	-
1	X MAX EMBLEM (SN)(CONSISTENT)	NOT NECESSARY	120.00	-
			1,150.00	300.00
<b><u>LABOUR</u></b>				
	TOWING FEES.	NOT NECESSARY	40.00	-



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE & REPLACE NECESSARY PARTS ,ALIGN & ETC.INCLUSIVE OF THE REPAIR OF RH BODY CENTRE PANEL.		280.00	150.00
	REMOVE & REPLACE FORK TUBE ,BRACKET,TOP UP FORK OIL & EXHAUST PIPE.		180.00	60.00
	PUTTY & TOUCH UP PAINT WORK.		250.00	120.00
			750.00	330.00
<b>GRAND TOTAL</b>			<b>7,718.50</b>	<b>3,600.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,800.00</b>

Report Ref No. CC4/ASM21005018/Dpa3q2

**ANG BRYAN TANI**

**Automotive Assessor / Investigator**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.