



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                         |  |   |  |                |
|---|--|---|--|----------------|
| AXA INSURANCE PTE LTD<br>8 SHENTON WAY #24-01<br>AXA TOWERSINGAPORE 068811<br>ATTN:WINNIE |  |   | Ref: CC4/ASM21005018/Dpa3q2<br>Date: 04/04/2022<br>Code: ASM |                |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>   |  |   |  |                |
|   | <b>Insured Veh.</b>  | GBC 9859R   | <b>Veh. Inspected</b>  | FBS 317M       |
|   | <b>Policy No.</b>  | P2427896  | <b>Coverage (\$)</b>   | 0.00           |
|   | <b>Claim No.</b>   | S1M03851  | <b>Excess (\$)</b>   | 0.00           |
|   | <b>Assign From</b>   |   | <b>Assign Date</b>   | 21/04/2021     |
| <b>2. Vehicle Particulars &amp; Condition</b>   |  |   |  |                |
|   | <b>Make &amp; Model</b>  | YAMAHA CZD300A  | <b>c.c</b>   | 292            |
|   | <b>Engine No.</b>  | HIDDEN  | <b>Year of Reg.</b>  | 2020           |
|   | <b>Chassis No.</b>   | MH3SH0845LK012521   | <b>Colour</b>  | BLACK          |
|   | <b>Odometer</b>  | -   | <b>Steering</b>  | IN ORDER       |
|   | <b>Brakes</b>  | IN ORDER  | <b>Modification</b>  | SPORTS RIM     |
|   | <b>General</b>   | GOOD  |  |                |
| <b>3. Conditions of Tyres</b>   |  |   |  |                |
|   |  | <b>Size</b>   | <b>Make</b>  | <b>Balance</b> |
|   | <b>R/H Front Tyre</b>  | 120/70 R15  | DUNLOP   | 2 mm           |
|   | <b>L/H Front Tyre</b>  |   |  | mm             |
|   | <b>R/H Rear Tyre</b>   | 140/70 R14  | DUNLOP   | 2 mm           |
|   | <b>L/H Rear Tyre</b>   |   |  | mm             |
| <b>4. Description of Damages</b>  |  |   |  |                |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.<br><br>DAMAGES SEE DETAILS.   |   |  |                |
| <b>5. General Information</b>   |  |   |  |                |
|   | <b>Accident Date</b>   | 14/04/2021  | <b>Inspection Date</b>                                       | 22/04/2021     |
|   | <b>Survey held at</b>  | SG 98 MOTOR PTE LTD<br>BLK 4001 ANG MO KIO INDUSTRIAL PARK 1<br>#01-21 SINGAPORE 569622 |  |                |
| <b>5a. Remarks</b>  |  |   |  |                |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |  |                |
| <b>5b. Estimate Days of Repair</b>  |  |   |  |                |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR:  |   | <b>4 Working Days</b>  |                |