



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21005031/Uqf3n2	
			Date: 11/05/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 4277Y	Veh. Inspected	SMY 906B	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2101271/RUC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	22/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COROLLA AXIO (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	NZE1416039749	Colour	GREY	
Odometer	211188 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/70 R14	MICHELIN	6 mm	
L/H Front Tyre	185/70 R14	MICHELIN	6 mm	
R/H Rear Tyre	185/70 R14	MICHELIN	6 mm	
L/H Rear Tyre	185/70 R14	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION AND REAR WINDSCREEN SHATTERED.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/04/2021	Inspection Date	22/04/2021	
Survey held at	IMPERIUM AUTOMOTIVE 25 KAKI BUKIT ROAD 4 #01-49 SYNERGY @ KB SINGAPORE 417800			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			12 Working Days	