

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21005041/TITF3N2**Date:** 20/08/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00113812002	
Claimant Vehicle No :	GBK3733S	Insured Vehicle No :	GBG8727Z	
Date of Loss:	15/04/2021	Nature of Claim:	TP	Claim No: SNM21D202228/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK3733S		Engine No:	YD25068040B
Make & Model:	NISSAN NV350, 2.5 (A)		Chassis No:	JN1MC2E26Z0032050
Reg. Date:	29/06/2020 (Man. Year: 2019)		Odometer:	48337 km
Colour:	Blue			
Engine Capacity:	2488 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	195R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,111.47	3,466.79	3,644.68	51.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,800.00	1,640.00	1,160.00	41.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,911.47	5,106.79	4,804.68	48.48
Approved Total (Overridden) (\$\$)		4,100.00		
(\$\$)	9,911.47	4,100.00	5,811.47	58.63
+ GST 7.00/7.00% (\$\$)	693.80	287.00	406.80	58.63
Nett Amount (\$\$)	10,605.27	4,387.00	6,218.27	58.63

INSPECTION

Date of Assignment:	22/04/2021	
Date Inspected:	23/04/2021 Inspected At:	Efficient Motor & Engineering Works Pte Ltd (HQ) 56 Loyang Way #06-07, Loyang Enterprise Building Singapore 508775
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 20 Aug 2021)	
Parts:	N/A	NISSAN NV350 2.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK3733S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	667.20 FL	*667.20 FL
2	6		*REAR BUMPER SIDE CLIP LH/RH	Not Necessary	72.60 FL	*- FL
3	1		*REAR BUMPER STEP PANEL	Repair	252.30 FL	*- FL
4	1		*REAR END PANEL OUTER	Repair	360.90 FL	*- FL
5	1		*TAILGATE	Bent	2,280.00 FL	*2,160.00 FL
6	1		*TAILGATE LOCK LOWER	Bent	528.60 FL	*261.00 FL
7	1		*TAILGATE LOCK UPPER	Not Necessary	178.80 FL	*- FL
8	1		*TAILGATE LOCK COVER	Cracked	84.00 FL	*84.00 FL
9	1		*TAILGATE LOCK ACTUATOR	Not Necessary	408.40 FL	*- FL
10	1		*TAILGATE WEATHER STRIP	Cut	228.00 FL	*180.80 FL
11	1		*TAILGATE CHROME GARNISH	Not Necessary	535.70 FL	*- FL
12	2		*TAILGATE ABSORBER LH/RH	Not Necessary	431.80 FL	*- FL
13	1		*TAILGATE LOGO	Necessary	115.20 FL	*59.70 FL
14	1		*TAILGATE EMBLEM NV350 URBAN	Necessary	156.00 FL	*50.40 FL
15	2		*TAIL LAMP LH/RH	Not Necessary	576.80 FL	*- FL
16	2		*REAR NUMBER PLATE LAMP	Not Necessary	192.00 FL	*- FL
17	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
18	1		*70KM/H STICKER	Necessary	20.00 FS	*20.00 FS
19	1		*REVERSE SENSOR	Not Working	200.00 FS	*200.00 FS
20	1		*REAR NO PLATE	Not Necessary	40.00 FS	*- FS
21	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
22	1		*PAN PACIFIC METAL PLATE	Necessary	80.00 FS	*40.00 FS
23	1		*REAR PANEL CHECKER PLATE	Not Necessary	80.00 FS	*- FS
24	1		*REAR FLOOR WOODEN PLANK	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,818.30	3,813.10
- List Item Discount on L Items 10.00/10.00% (\$\$)	706.83	346.31
Total Parts (\$\$)	7,111.47	3,466.79

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT/WELD PANELS,PANEL BEAT & ALIGN TAILGATE,REMOVE & REPLACE DAMAGED PARTS	New	1,200.00	700.00
2	TO APPLY ANTI RUST COAT AND TUFF KOTE REPAIRED AREAS	New	150.00	30.00
3	TO CHECK AND RECTIFY LIGHTING & WIRING	New	50.00	0.00
4	TO REMOVE & REPLACE REVERSE SENSOR	New	100.00	30.00
5	TO SPRAY PAINTING FOR REAR PORTIONS & AFFECTED AREAS	New	1,000.00	700.00
6	TO REMOVE & TRANSFER TAILGATE COMPONENTS	New	150.00	60.00
7	TO REMOVE AND REPLACE REAR WINDSCREEN GLASS	New	150.00	120.00
Gross Labour Cost (\$)			2,800.00	1,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >