

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21005047/KPA3Q2**Date:** 16/02/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800088239
Claimant Vehicle No :	SJN3649S	Insured Vehicle No :	SKJ5070G
Date of Loss:	20/04/2021	Nature of Claim:	TP
		Claim No:	1471227558SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJN3649S	Engine No:	1ZZ3226141
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	JTDER12W303001791
Reg. Date:	12/02/2009 (Man. Year: 2009)	Odometer:	147328 km
Colour:	Metallic Black		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,835.58	4,345.48	490.10	10.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,010.00	1,500.00	510.00	25.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,845.58	5,845.48	1,000.10	14.61
Approved Total (Overridden) (S\$)		4,650.00		
(S\$)	6,845.58	4,650.00	2,195.58	32.07
+ GST 7.00/7.00% (S\$)	479.19	325.50	153.69	32.07
Nett Amount (S\$)	7,324.77	4,975.50	2,349.27	32.07
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
Nett Liability (S\$)		5,475.50		

INSPECTION

Date of Assignment:	22/04/2021	
Date Inspected:	26/04/2021	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	627.20 FL	*627.20 FL
2	1		*REAR BUMPER RH REFLECTOR	Serviceable	57.90 FL	*- FL
3	1		*REAR BUMPER RH REINFORCEMENT BRACKET	Dented	53.80 FL	*53.80 FL
4	1		*REAR BUMPER RH SIDE RETAINER	Distorted	69.40 FL	*69.40 FL
5	5		*REAR BUMPER CLIP	Necessary	21.00 FL	*21.00 FL
6	2		*TAILLAMP	Cut	1,193.40 FL	*1,130.20 FL
7	1		*REAR TAILGATE	Bent	1,620.70 FL	*1,429.10 FL
8	1		*TAILGATE INNER LOCK	Jammed	539.90 FL	*389.10 FL
9	1		*TAILGATE INNER RUBBER (50%)	Dented	277.43 FS	*184.95 FS
10	1		*TAILGATE INNER TRIM BOARD	Mtg Distorted	373.80 FL	*373.80 FL
11	1		*TAILGATE WINDSCREEN MOULDING	Necessary	70.20 FL	*70.20 FL
12	1		*TAILGATE LOGO	Necessary	49.27 FL	*49.27 FL
13	1		*REAR END PANEL	Bent	590.60 FL	*590.60 FL
14	1		*REAR END PANEL INNER TOP GARNISH	Mtg Cracked	283.70 FL	*283.70 FL
15	1		*REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
16	1		*REAR NUMBER PLATE	Dented	35.00 FS	*35.00 FS
17	1		*REAR BUMPER STEP GARNISH	Necessary	80.00 FS	*40.00 FS
18	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
19	1		*REAR END PANEL SEALANT	Necessary	40.00 FS	*30.00 FS
					Sub Total (S\$)	6,223.30 5,617.32
					- List Item Discount on L Items 25.00/25.00% (S\$)	1,387.72 1,271.84
					Total Parts (S\$)	4,835.58 4,345.48

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX REAR BUMPER & ATTACHMENTS TAILGATE & ATTACHMENTS ,TAILLAMPS TO CUT ,WELD & RENEW REAR END PANEL ,KNOCKING & REPAIR REAR LUGGAGE PANEL ,REAR FENDERS & REALIGN THE SAME	New	900.00	600.00
2	PUTTY & RESPRAY REAR BUMPER & PARKING SENSORS ,TAILGATE BOTH FENDERS ,REAR END PANEL ,REAR LUGGAGE PANEL & ALL AFFECTED AREAS	New	900.00	720.00
3	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
4	RUSTPROOFING	New	90.00	60.00
Gross Labour Cost (\$)			2,010.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >