

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21005049/KGS3Q2
Date: 17/12/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070144544
Claimant Vehicle No :	ES2330A	Insured Vehicle No :	GBE2962K
Date of Loss:	17/04/2021	Nature of Claim:	TP
		Claim No:	3197830540SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	ES2330A		
Make & Model:	BMW 216D, 1.5 D GRAN TOURER LED NAV 7 SEATER (A)	Engine No:	30219523B37C15A
Reg. Date:	27/06/2016 (Man. Year: 2016)	Chassis No:	WBA2E320005B44921
Colour:	Metallic Pearl White	Odometer:	30689 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R17	Rear Tyre Size:	205/55 R17
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,683.50	3,822.79	1,860.71	32.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,040.00	1,070.00	970.00	47.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,723.50	4,892.79	2,830.71	36.65
Approved Total (Overridden) (S\$)		3,900.00		

	(S\$)	7,723.50	3,900.00	3,823.50	49.50
+ GST 7.00/7.00% (S\$)		540.65	273.00	267.65	49.51
Nett Amount (S\$)		8,264.15	4,173.00	4,091.15	49.50
+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$)			428.00		
+ Doc/Search Fee (S\$)			2.00		
Nett Liability (S\$)			4,603.00		

INSPECTION

Date of Assignment: 22/04/2021

Date Inspected: 22/04/2021

Estimated Period of Repair: 4.0 days

Inspected At:

MBM Wheelpower Pte Ltd (HQ)
 160 Sin Ming Drive #06-02, Sin Ming AutoCity
 Singapore 575722

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	1,700.00 FL	*1,220.00 FL
2	1		*FRONT BUMPER RH RETAINER	Serviceable	55.00 FL	*- FL
3	1		*FRONT RH FOG LAMP BRACKET	Cracked	175.00 FL	*175.00 FL
4	1		*FRONT RH FOG LAMP CHROME	Missing	157.00 FL	*125.00 FL
5	1		*FRONT RH FOG LAMP COVER	Distorted	143.00 FL	*122.80 FL
6	1		*FRONT RH FOG LAMP	Mtg Cracked	325.00 FL	*245.00 FL
7	2		*PARKING SENSOR -BLACK	Serviceable	640.00 FL	*- FL
8	1		*DECOULPING RING	Serviceable	60.00 FL	*- FL
9	1		*HEAD LAMP RH	Cracked	3,060.00 FL	*2,359.75 FL
F=Franchise part. L=ListItemDisc.						
					Sub Total (S\$)	6,315.00
					- List Item Discount on L Items 10.00/10.00% (S\$)	631.50
					Total Parts (S\$)	5,683.50
						4,247.55
						424.76
						3,822.79

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE REFIT & REPAIR AFFECTED DAMAGED PARTS .INCLUDING TO KNOCK -OUT ,WELD & STRAIGHTEN ON THE AFFECTED PARTS	New	800.00	350.00
2	TO RESET ENGINE WARNING LIGHT (ABS ,SRS,ECU MEMORY & ETC)	New	300.00	200.00
3	TO REMOVE & REPLACE BUMPER SENSORS	New	60.00	60.00
4	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	80.00	20.00
5	TO SPRAY PAINT ON THE AFFECTED AREAS	New	800.00	440.00
Gross Labour Cost (\$)			2,040.00	1,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >