

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/GRB21005051/T1BS3Q2  
**Date:** 05/07/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
<b>Claimant Vehicle No :</b>	SHC606S	<b>Insured Vehicle No :</b>	SMY9001C
Date of Loss:	20/04/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0001819

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHC606S</b>		
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Engine No:	G4LEKU363646
Reg. Date:	09/10/2019 (Man. Year: 2019)	Chassis No:	KMHC851CVLU178999
Colour:	Yellow	Odometer:	115035 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,236.32	566.00	670.32	54.22
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	840.00	630.00	210.00	25.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,087.32</b>	<b>1,207.00</b>	<b>880.32</b>	<b>42.17</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>146.11</b>	<b>84.49</b>	<b>61.62</b>	<b>42.17</b>

<b>Nett Amount (S\$)</b>	<b>2,233.43</b>	<b>1,291.49</b>	<b>941.94</b>	<b>42.17</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

INSPECTION

Date of Assignment:	22/04/2021	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	22/04/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang)
Estimated Period of Repair:	2.0 days		59 Loyang Drive Singapore 508969

---

**Adjuster:** MOHD TAUFIKH BIN HAMID

---

**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jul 2021)
<b>Parts:</b>	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC606S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Repair	459.40 FL	*- FL
2	1		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
3	1		*REAR BUMPER CENTRE MOULDING ASSY	Deformed	451.25 FL	*451.25 FL
4	1		*REAR BUMPER LOWER CTR MOULDING	Repair	155.00 FL	*- FL
5	1		*REAR BUMPER FOG LAMP	Not Necessary	201.50 FL	*- FL
6	1		*REAR NUMBER PLATE	Cracked	25.00 F	*25.00 F
7	1		*REAR BUMPER REVERSE SENSOR	Necessary	180.00 F	*180.00 F
					<b>Sub Total (\$\$)</b>	<b>1,494.15</b>
					<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>257.83</b>
					<b>Total Parts (\$\$)</b>	<b>1,236.32</b>
						<b>566.00</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
<b>Sub Total (S\$)</b>			<b>11.00</b>	<b>11.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINTING CHARGE	New	300.00	250.00
3	WIRING CHARGE	New	60.00	0.00
4	REMOVE AND REFIX REVERSE SENSOR	New	80.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>840.00</b>	<b>630.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >