

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21005058/ARA3Q2
Date: 05/01/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700071016
Claimant Vehicle No :	SFP8181C	Insured Vehicle No :	SKF1982Y
Date of Loss:	21/04/2021	Nature of Claim:	TP
		Claim No:	7223423145SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFP8181C		
Make & Model:	HYUNDAI TUCSON, 1.6 TL GLS (A)	Engine No:	G4FJLH805404
Reg. Date:	16/12/2020 (Man. Year: 2020)	Chassis No:	KMHJ3812VLU379646
Colour:	White	Odometer:	5876 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/60 R17	Rear Tyre Size:	225/60 R17
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,172.00	7,249.44	5,922.56	44.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	730.00	2,470.00	77.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,372.00	7,979.44	8,392.56	51.26
Approved Total (Overridden) (S\$)		6,300.00		

(S\$)	16,372.00	6,300.00	10,072.00	61.52
+ GST 7.00/7.00% (S\$)	1,146.04	441.00	705.04	61.52
Nett Amount (S\$)	17,518.04	6,741.00	10,777.04	61.52
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,348.45		

INSPECTION

Date of Assignment: 22/04/2021

Date Inspected: 23/04/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Cas Garage Pte Ltd (HQ)
No.1, Kaki Bukit Ave 6, #02-22 Autobay
Singapore 417883

Adjuster: ADRIAN LING**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Not Necessary	1,852.30 FL	*- FL
2	1		*FRONT BONNET INSULATOR	Not Necessary	224.30 FL	*- FL
3	1		*FRONT BONNET RUBBER SEAL	Not Necessary	85.00 FL	*- FL
4	1		*FRONT HEADLAMP RH	Cut	5,867.80 FL	*5,867.80 FL
5	1		*FRONT HEADLAMP BRACKET RH	Not Necessary	98.30 FL	*- FL
6	1		*FRONT HEADLAMP TOP GARNISH RH	Not Necessary	85.40 FL	*- FL
7	1		*FRONT BUMPER	Deformed	559.50 FL	*559.50 FL
8	1		*FRONT BUMPER LOWER	Cut	431.40 FL	*431.40 FL
9	1		*FRONT BUMPER SIDE RETAINER RH	Damaged	68.40 FL	*68.40 FL
10	1		*FRONT BUMPER ATTACHMENT BRACKET	Cracked	98.30 FL	*98.30 FL
11	1		*FRONT BUMPER TOW COVER	Not Necessary	42.60 FL	*- FL
12	1		*FRONT BUMPER LOWER LID	Not Necessary	245.60 FL	*- FL
13	1		*FRONT NUMBER PLATE GARNISH	Not Necessary	65.30 FL	*- FL
14	1		*FRONT BUMPER RADIATOR GRILLE	Cut	751.80 FL	*751.80 FL
15	1		*FRONT BUMPER RADIATOR GRILLE LOGO	Not Necessary	85.30 FL	*- FL
16	4		*FRONT BUMPER SENSOR	Not Necessary	676.00 FL	*- FL
17	1		*FRONT BUMPER SENSOR GARNISH	Not Necessary	138.60 FL	*- FL
18	1		*FRONT BUMPER FOG LAMP RH	Not Necessary	757.10 FL	*- FL
19	1		*FRONT BUMPER FOG LAMP GARNISH RH	Cut	126.40 FL	*126.40 FL
20	1		*FRONT BUMPER REINFORCEMENT	Dented	653.60 FL	*653.60 FL
21	1		*FRONT BUMPER REINFORCEMENT SPONGE	Cracked	141.20 FL	*141.20 FL
22	1		*FRONT BUMPER LOWER STIFFENER	Not Necessary	224.90 FL	*- FL
23	1		*FRONT SUPPORT PANEL	Not Necessary	987.80 FL	*- FL
24	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	265.80 FL	*- FL
25	1		*FRONT SUPPORT PANEL AIR GUIDE RH	Not Necessary	64.20 FL	*- FL
26	1		*WIPER WASHER TANK ASSY	Deformed	130.70 FL	*130.70 FL
27	1		*WIPER WASHER TANK MOTOR	Not Necessary	89.50 FL	*- FL
28	1		*FRONT FENDER RH	Not Necessary	1,227.70 FL	*- FL
29	1		*FRONT FENDER PROTECTOR RH	Cut	195.20 FL	*195.20 FL
30	1		*FRONT NUMBER PLATE W CASING	Not Necessary	60.00 FS	*- FS
31	1		*SET BONNET INSULATOR CLIPS	Not Necessary	30.00 FS	*- FS
32	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
33	1		*SET SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
34	1		*SET FRONT FENDER CLIPS	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Sub Total (S\$)	16,420.00
					- List Item Discount on L Items 20.00/20.00% (S\$)	3,248.00
					Total Parts (S\$)	13,172.00

9,054.30**1,804.86****7,249.44**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT/ STRAIGHTEN /REALIGN ACCIDENT AFFECTED AREAS	New	1,500.00	300.00
2	TO RESPRAY ACCIDENT AFFECTED PORTION	New	1,200.00	400.00
3	TO DISMANTLE REPLACE AND /OR REPAIR AIR CON CONDENSER & REFILL AIR CON GAS	New	150.00	0.00
4	TO DISMANTLE ,REPLACE AND/OR REPAIR RADIATOR AND PRESSURE TEST	New	150.00	0.00
5	TO CHECK WIRING /WIRE CONNECTOR AND REWIRE /REPAIR	New	100.00	30.00
6	TO CHECK AND REALIGN HEADLAMP	New	100.00	0.00
Gross Labour Cost (\$\$)			3,200.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >