

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21005059/T1PA3Q2
Date: 16/08/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070013782
Claimant Vehicle No :	SHA2879T	Insured Vehicle No :	GBE6493X
Date of Loss:	21/04/2021	Nature of Claim:	TP
		Claim No:	2952583324SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA2879T		
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Engine No:	G4LEKU397232
Reg. Date:	22/10/2019 (Man. Year: 2019)	Chassis No:	KMHC851CVLU186567
Colour:	Blue	Odometer:	0 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,634.92	2,227.48	407.44	15.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,690.00	1,145.00	545.00	32.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,324.92	3,372.48	952.44	22.02
+ GST 7.00/7.00% (S\$)	302.74	236.07	66.67	22.02

Nett Amount (\$\$)	4,627.66	3,608.55	1,019.11	22.02
+ Loss of Use (4.0 x S\$50.00/day) (\$\$)		200.00		
+ Car Rental (4.0 x S\$125.19/day) (\$\$)		500.76		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		4,311.31		
Global Sum Settlement (\$\$)		4,300.00		

INSPECTION

Date of Assignment: 22/04/2021

Date Inspected: 23/04/2021

Estimated Period of Repair: 3.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	459.40 FL	*459.40 FL
2	2		*REAR BUMPER SIDE BRACKET LH/RH	Not Necessary	111.60 FL	*- FL
3	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
4	1		*REAR BUMPER REINFORCEMENT	Cracked	394.80 FL	*394.80 FL
5	2		*REAR BUMPER REINFORCEMENT BRACKET LH/RH	Bent	276.20 FL	*276.20 FL
6	1		*REAR BUMPER LOWER MOULDING	Missing	155.00 FL	*155.00 FL
7	1		*REAR BUMPER FOG LAMP	Not Necessary	201.50 FL	*- FL
8	2		*NUMBER PLATE LAMP LH/RH	Cracked (1 PCS ONLY)	170.60 FL	*85.30 FL
9	1		*REAR BUMPER CENTRE MOULDING	Deformed	451.25 FL	*451.25 FL
10	1		*EMBLEM -IONIQ	Necessary	31.30 FL	*31.30 FL
11	1		*BOOT LID HYBRID PLATE	Necessary	24.30 FL	*24.30 FL
12	1		*BOOT LID H EMBLEM	Not Necessary	28.00 FL	*- FL
13	2		*REAR BUMPER REFLECTOR LH/RH	Not Necessary	82.90 FL	*- FL
14	1		*REAR FLOOR UNDER	Cracked	225.00 FL	*225.00 FL
15	1		*SMART KEY ANTENNA	Cracked	40.50 FL	*40.50 FL
16	1		*REAR BUMPER TOW COVER	Missing	98.80 FL	*98.80 FL
17	1		*COVER RR BUMPER SIDE UNDER	Deformed	108.00 FL	*108.00 FL
18	1		*REAR NUMBER PLATE /W HOLDER	Missing	50.00 FS	*50.00 FS
19	1		*REAR REVERSE SENSOR	Not Working	180.00 FS	*180.00 FS
20	1		*COMFORT LOGO STICKER	Necessary	30.00 FS	*30.00 FS
21	1		*COMFORT APP STICKER	Necessary	40.00 FS	*40.00 FS
22	1		*TEL NUMBER STICKER	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,211.15	2,701.85
- List Item Discount on L Items 20.00/20.00% (\$\$)	576.23	474.37
Total Parts (\$\$)	2,634.92	2,227.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	850.00	525.00
2	SPRAY PAINTING CHARGE	New	600.00	500.00
3	CHECK WIRING	New	60.00	30.00
4	TUFF KOTE	New	60.00	0.00
5	REMOVE/REFIX REVERSE SENSOR	New	60.00	30.00
6	TOWING	New	60.00	60.00
Gross Labour Cost (\$\$)			1,690.00	1,145.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >