



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. ET 128B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	HEADLAMP (BI-XENON) RH	NOT NECESSARY	2,495.00	-
1	HEADLAMP BRACKET RH	CRACKED	81.00	81.00
1	FRT BUMPER (M/SPORT)	DENTED / DEFORMED	1,351.00	1,351.00
1	FRT BUMPER FOG LAMP RH	REFIT	287.00	-
1	FRT BUMPER FOG LAMP BRACKET RH	CRACKED	62.00	62.00
1	FRT FENDER RH	TO REPAIR SEE LABOUR	757.00	-
1	FRT FENDER COWLING RH	NOT NECESSARY	149.00	-
1	FRT SPORT RIM RH (ET:34, M/SPORT)	TO REPAIR SEE LABOUR	965.00	-
1	FRT WHEEL HUB ASSY RH	NOT NECESSARY	489.00	-
1	FRT CARRIER RH	NOT NECESSARY	449.00	-
1	FRT ADIUS ROD RH	NOT NECESSARY	229.00	-
1	FRT WISHBONE RH	NOT NECESSARY	225.00	-
1	FRT STABILIZER BAR	NOT NECESSARY	378.00	-
1	FRT STABILIZER LINK RH	NOT NECESSARY	102.00	-
1	FRT FENDER RH (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 5% DISCOUNT		-400.95	-74.70
			7,618.05	1,419.30
<u>SPECIAL NETT ITEMS</u>				
1	FRT TYRE RH (SN)	NOT NECESSARY	450.00	-
1	SET FRT SUSPENSION COILOVER (SN)	NOT NECESSARY	1,400.00	-
1	BOT BRAKE FLUID (SN)	NOT NECESSARY	20.00	-
1	SET FRT BUMPER SIDE SKIRT (CF) (SN)	NOT NECESSARY	600.00	-
			2,470.00	-
<u>LABOUR</u>				
	TO CHECK ELECTRICAL SYSTEM AND CALIBRATE / FOCUS HEADLAMP.		60.00	50.00
	TO REMOVE, CHECK AND REPLACE RHF UNDERCARRIAGE PARTS. (INCLUDE FLUSH AND BLEED BRAKES SYSTEM).	NOT NECESSARY	250.00	-

Report Ref No. CS1/LAW21005061/Dvf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CONDUCT WHEEL ALIGNMENT (2X).		120.00	120.00
	TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS.		600.00	440.00
	TO SPRAY PAINTING, BLENDING ON AFFECTED AND ADJACENT AREA.		600.00	450.00
			1,630.00	1,060.00
GRAND TOTAL			11,718.05	2,479.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,000.00

Report Ref No. CS1/LAW21005061/Dvf3e2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.