

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE	PTE LTD	Ref:	CS3/ASM21005063/Btce2	
	8 SHENTON WAY TOWERSINGAPOR	-	Date:	30/04/2021	
	ATTN: YU DOMINI	C YISHAN	Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHC 7301A	Veh. Inspected	SMX 7182G	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	S1M038OK	Excess (\$)	0.00	
	Assign From	YU DOMINIC YISHAN	Assign Date	23/04/2021	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA RAV4 HYBRID	c.c	2487	
	Engine No.	HIDDEN	Year of Reg.	2021	
	Chassis No.	JTMZ23FV90D056873	Colour	BLACK	
	Odometer	5053 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	235/55 R18	MICHELIN	7 mm	
	L/H Front Tyre	235/55 R18	MICHELIN	7 mm	
	R/H Rear Tyre	235/55 R18	MICHELIN	7 mm	
	L/H Rear Tyre	235/55 R18	MICHELIN	7 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.				
5.	General Information				
	Accident Date	21/04/2021	Inspection Date	23/04/2021	
	Survey held at	EXCEL MOTOR			
	BLK 5032 ANG MO KIO INDUSTRIAL PARK 2 #01-297 SINGAPORE 569535				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000				
5b.	Estimate Days of Repair				
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days			