

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 7286S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEFORMED / TORN	975.00	975.00
2	FRONT BUMPER RETAINER @\$19.90	O/S BENT	39.80	19.90
1	FRONT BUMPER REINFORCEMENT	BENT	593.00	466.80
1	FOG LAMP COVER RH	GRAZED	45.00	45.00
1	FOG LAMP RH	NOT FITTED	164.00	-
1	FRONT GRILLE ASSY	CRACKED	126.00	126.00
1	FRONT EMBLEM	NOT NECESSARY	46.00	-
1	HEAD LAMP RH	CRACKED	812.00	812.00
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	349.00	-
1	FRONT FENDER INNERSHIELD RH	NOT NECESSARY	135.00	-
1	SUPPORT PANEL	NOT NECESSARY	492.00	-
1	WASHER TANK	DEFORMED	109.20	109.20
1	FRT BUMPER INNER BRACKET O/S	CRACKED	45.50	45.50
	LESS 20% DISCOUNT		-786.30	-519.88
			3,145.20	2,079.52
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	50.00	50.00
1	SET FRONT FENDER INNERSHIELD CLIP (SN)	NOT NECESSARY	50.00	-
1	FRONT NUMBER PLATE WITH CASING (SN)	NOT NECESSARY	50.00	-
			150.00	50.00
	<u>LABOUR</u>			
	TO CHECK WIRING SYSTEM.		80.00	20.00
	TO PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT FENDER RH.		800.00	300.00
	TO SPRAY PAINTING.		800.00	560.00
	TO CONDUCT 4 WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
			1,800.00	880.00
	GRAND TOTAL		5,095.20	3,009.52
			1	

Report Ref No. CS/AGI21005070/Uqf3n2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,400.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/AGI21005070/Uqf3n2

CHUA KANG SENG
Licensed Appraiser