

### Advanced Automotive Consultancy Pte Ltd

Bussiness Regn No: 201416413W

#### **ACCIDENT VEHICLE INSPECTION / ASSESSMENT REPORT**

1 REFERENCE

Our reference no : TP/FBL3431H/EB/0220/03

Date of request : 11-Feb-2020 Date of survey : 11-Feb-2020 Date of accident : 6-Feb-2020

Requested by : DINIE SYAKIR BIN RAZALI

C/o , Blk 25 Kaki Bukit Rd 4 Synergy@KB, #03-79.Singapore 417800

Type of claim : Third party

Workshop : EQUATOR BROTHERHOOD

Blk 25, Kaki Bukit Rd 4 Synergy@KB, #03-79

Singapore 417800

2 DETAILS OF VEHICLE

Registration No. : FBL3431H

Make & Model : YAMAHA MT-09 ABS TRACER

Date of registration : 5-Sep-2016 : N701E067522 Engine No. Engine No.
Engine Capacity

: 847CC

Chassis No. : JYARN29K000001056

Speedometer reading : 66,816KM Colour : GREY

3 STATIC CHECK

Steering : In order Paintwork : Good Footbrake : In order Modification : Nil Handbrake : In order General condition : Good

4 TYRE CONDITION

Nearside/Make Front tyre : 3mm/Metzeler 120/70zr17 Rear tyre : 3mm/Metzeler 180/55ZR17

5 POINT OF IMPACT

The said vehicle has sustained an impact damages on the rear, front and left side portion. Kindly refer to the attached photographs for more detail of the damages.

6 REMARK

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not authorised any repair.

Address: 159, Yishun St 11, #04-166 S(760159)

# Advanced Automotive Consultancy Pte Ltd

# Annex A: Assessement / Adjustment on Spare Parts

TP/FBL3431H/EB/022	20/03	
--------------------	-------	--

tem	Vehicle Parts Description	Condition	Qty	W/shop Est. (\$)	Disc (%)	Adjusted Cost (\$)
	List Items		- 1	E30 (4)	(70)	0001(4)
1	Yamaha front suspension	distorted/stiffened	2	\$2,700.00	10%	\$2,430.00 NN
2	Yamaha triple clamp (top)	serviceable	1	\$450.00	100%	\$0.00 HM
3	Yamaha triple clamp (bottom)	serviceable	1	\$580.00	100%	\$0.00 HH
4	Yamaha steering cone bearing	not necessary	1	\$180.00	100%	\$0.00 NN
5	Yamaha handle bar	distorted	1	\$280.00	10%	\$252.00 HN
6	Yamaha front wheel bearing	intact	2	\$70.00	100%	\$0.00 HN
7	Yamaha front wheel seal	intact	2	\$30.00	100%	\$0.00 NN
8	Yamaha front wheel shaft	intact	1	\$120.00	100%	\$0.00 NN
9	Yamaha headlight panel (carbon	grazed	2	\$200.00	10%	\$180.00 MM
	fiber look)	3,444	_	4200.00		4100.00   1111
10	Yamaha headlight (left)	intact	1	\$350.00	100%	\$0.00 NH
11	Yamaha headlight (right)	grazed	1	\$350.00	10%	\$315.00 SYC
12	Yamaha headlight fairing (left)	grazed	1	\$120.00	10%	\$108.00
13	Yamaha headlight fairing (right)	repair	1	\$120.00	100%	\$0.00 HN
14	Yamaha rear number plate holder	deformed/bent	1	\$80.00	10%	\$72.00
15					10%	\$99.00
10	Yamaha rear number plate holder bracket	bent	1	\$110.00	10%	\$99.00
16		ararad		\$20.00	10%	\$18.00 5/4
10	Yamaha rear number plate	grazed	1	\$20.00	1070	\$10.00 )
47	reflector (yellow) (Right hand)	Introd	1	\$2F.00	1000/	\$0.00 NN
17	Yamaha rear number plate	intact	1	\$25.00	100%	PIN 00.0¢
40	reflector (red)	talast.		400.00	4000/	14.00.00
18	Yamaha rear number plate light	intact	1	\$80.00	100%	\$0.00 N N
40	assembly	to to a t	BEST	£4E 00	1000/	60 00 km
19	Yamaha rear number plate light	intact	1	\$15.00	100%	\$0.00 HH
20	COVER Versels along light	distanted/arrand	2	\$130.00	10%	\$117.00
20	Yamaha rear signal light	distorted/grazed cracked	1	\$50.00	10%	\$45.00
21	Yamaha front sprocket cover		1	\$150.00	10%	\$135.00 3/6
22	Yamaha rider footrest bracket (left)	grazed	1	\$150.00	10 /0	\$100.00
23	Yamaha rider footrest (left)	grazed	1	\$55.00	10%	\$49.50
24	Yamaha rider footrest pin (left)	necessary	1	\$15.00	10%	\$13.50
25	Yamaha rider footrest spring (left)	necessary	1	\$10.00	10%	\$9.00
	Yamaha rider footrest holder (left)	necessary	1	\$15.00	10%	\$13.50
	Yamaha rider footrest safety	grazed	1	\$5.00	10%	\$4.50
27	distance screw (left)	grazed		Ψ0.00	1070	V
20	Yamaha mirror (left)	grazed	.1	\$110.00	10%	\$99.00
28		grazed	2	\$130.00	10%	\$117.00
29	Yamaha handguard cover (black)	bent	2	\$160.00	10%	\$144.00 NN
	Yamaha handguard bracket		1	\$280.00	10%	\$252.00
31	Yamaha side pannier box bracket	grazed/bent		\$200.00	1076	φ202.00
20	Set	intact	2	\$300.00	100%	\$0.00 NN
32	Yamaha fuel tank cover (carbon	intact	2	\$300.00	10070	Ψ0.00 1414
	fiber look)	ropoir	4	\$130.00	100%	\$0.00 HN
33	Yamaha pillion footrest bracket	repair	1	\$130.00	100%	\$0.00 1414
	(left)	aranad		£45.00	100/	\$40.50 \
34	Yamaha pillion footrest (left)	grazed	1	\$45.00	10%	\$40.50
35	Yamaha pillion footrest pin (left)	necessary	1	\$15.00	10%	\$13.50 \rightarrow \$4.50 \rightarrow
36	Yamaha pillion footrest bearing	necessary	1	\$5.00	10%	54 50

#### TP/FBL3431H/EB/0220/03

Item	Vehicle Parts Description	Condition	Qty	W/shop	Disc	Adjusted
Normal Heat				Est. (\$)	(%)	Cost (\$)
37	Yamaha gear shifter	bent/grazed	1	\$85.00	10%	\$76.50
38	Yamaha gear shifter tie rod	intact	1	\$40.00	100%	\$0.00 HH
39	Yamaha gear shifter arm	intact	1	\$40.00	100%	\$0.00 HN
40	Yamaha rear mudguard	deformed/grazed	1	\$75.00	10%	\$67.50
41	Yamaha rear mudguard bracket	bent/grazed	1	\$85.00	10%	\$76.50
42	Yamaha rear swingarm	distorted	1	\$1,250.00	10%	\$1,125.00 SVU
43	Yamaha rear swingarm bush	necessary	1	\$180.00	10%	\$162.00 NN
44	Yamaha rear swingarm shaft	serviceable	1	\$120.00	100%	\$0.00 7
45	Yamaha rear wheel bearing	intact	2	\$70.00	100%	\$0.00
46	Yamaha rear wheel seal	intact	2	\$30.00	100%	\$0.00 \ NN
47	Yamaha rear wheel shaft	intact (L+20·10)	1	\$120.00	100%	\$0.00
48	Yamaha front signal (left)	intact 1420 W grazed	1	\$65.00	10%	\$58.50 1946
		15761210	-	\$9,645.00	Selection of	\$6,097.50
	S/Nett Items					
1	Denali fog light cover (yellow)	grazed	1	\$50.00		\$50.00
2	Denali fog light set	grazed	1	\$680.00		\$680.00
3	The state of the s	grazed	1	\$380.00		\$380.00 514
4		necessary	1	\$15.00		\$15.00 HH
5		bent	1	\$20.00		\$20.00
6		scratched	1	\$750.00		\$750.00 516
7		necessary G2000	1	\$80.00		\$80.00 HN
8		grazed/bent	1	\$110.00		\$110.00 NH
5	Crash protection bar (left hand)	grazed/bent	1	\$180.00		\$180.00
				\$2,265.00		\$2,265.00
		Total for Spare Par	ts :_	\$11,910.00		\$8,362.50

## Advanced Automotive Consultancy Pte Ltd

### Annex B: Adjustment on Labour and Spray Painting

TP/FBL3431H/EB/0220/03

tem	Job Description Workshop Est. (\$)					
1	To remove & replace front wheel bearing, front steering cone.	fork,	\$300.00	\$180.00 HH		
2	To remove & replace above body damaged part wiring & lighting system	s,check	\$500.00	\$400.00 30		
3	To conduct chassis alignment		\$480.00	\$350.00 NN		
4	To remove DID X-ring chain to assist replaceme swing arm		\$250.00	\$180.00 HH		
5	Towing -workshop to accident reporting center	360-1	\$60.00	\$50.00 35		
6	Towing -accident reporting center to workshop		\$60.00	\$50.00 35 -		
			\$1,650.00	\$1,210.00		
	TOTAL FOR LABOUR & SPRAY P	AINTING :	\$1,650.00	\$1,210.00		

#### Summary

	Workshop Est. (\$)	Adjusted Cost (\$)	
TOTAL FOR SPARE PARTS : TOTAL FOR LABOUR & SPRAY PAINTING :	\$11,910.00 \$1,650.00	\$8,362.50 \$1,210.00	
TOTAL PEDAID COSTS .			

Most perts found not changed during of the repair indicated as suc

\* items indirable as HM
mostly not consistent or
Photos show no demage.

\* Dike Jell on light side offer Impact. 2568 W

4 days.