

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21005074/T1GS3Q2
Date: 17/08/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SKU4924S	Insured Vehicle No :	SGX561M
Date of Loss:	18/04/2021	Nature of Claim:	TP
		Claim No:	0391041005SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU4924S		
Make & Model:	MERCEDES-BENZ C180, 1.6 Avantgarde (R17 LED) (A)	Engine No:	27491030386808
Reg. Date:	30/07/2015 (Man. Year: 2015)	Chassis No:	WDD2050402R069143
Colour:	Black	Odometer:	75689 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,377.00	0.00	1,377.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	780.00	480.00	300.00	38.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,157.00	480.00	1,677.00	77.75
+ GST 7.00/7.00% (S\$)	150.99	33.60	117.39	77.75

Nett Amount (S\$)	2,307.99	513.60	1,794.39	77.75
+ Loss of Use (2.0 x S\$60.00/day) (S\$)		120.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		635.60		

INSPECTION

Date of Assignment: 23/04/2021

Date Inspected: 23/04/2021

Estimated Period of Repair: 2.0 days

Inspected At: Tan Lim Motor Pte Ltd (Defu)
1 Defu Lane 6
Singapore 539365

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Recommended Parts

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	350.00	250.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	30.00	0.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	300.00	200.00
4	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	100.00	30.00
Gross Labour Cost (S\$)			780.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >