

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21005075/AVCE2

**Date:** 30/08/2021

### REFERENCE

Insured/Claimant: LOH ZHI YI Policy No:  
Date of Loss: 16/04/2021 Nature of Claim: OD Claim No: 5346966071SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMU5810G**  
Make & Model: AUDI Q3, 1.4 TFSI (A) Engine No: CZD897537  
Reg. Date: 20/08/2020 (Man. Year: 2020) Chassis No: WAUZZZF3XL1115087  
Colour: White Odometer: 6944 km  
Engine Capacity: 1395 cc  
Market Value/New Car Price: S\$152,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/65 R17 Rear Tyre Size: 215/65 R17  
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm  
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,552.00	7,692.48	7,859.52	50.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,467.10	5,122.00	4,345.10	45.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>25,019.10</b>	<b>12,814.48</b>	<b>12,204.62</b>	<b>48.78</b>
<b>- Excess (S\$)</b>	800.00	800.00	0.00	0.00
<b>(S\$)</b>	24,219.10	12,014.48	12,204.62	50.39
<b>+ GST 7.00/7.00% (S\$)</b>	1,695.34	841.01	854.33	50.39
<b>Nett Amount (S\$)</b>	<b>25,914.44</b>	<b>12,855.49</b>	<b>13,058.95</b>	<b>50.39</b>

### INSPECTION

Date of Assignment: 23/04/2021  
Date Inspected: 22/04/2021 Inspected At: Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699  
Estimated Period of Repair: 7.0 days

**Adjuster:** ADRIAN LING

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER - RH	Repair	1,008.00 FS	*- FS
2	1		*FRONT BUMPER CONNECTING PIECE	Not Necessary	145.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	217.00 FS	*- FS
4	2		*FRONT BUMPER GRILLE - LH / RH	Not Necessary	220.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	190.00 FS	*- FS
6	1		*FRONT RADIATOR GRILLE	Not Necessary	1,433.00 FS	*- FS
7	1		*FRONT RADIATOR STRIKER PLATE	Not Necessary	244.00 FS	*- FS
8	1		*FRONT DOOR - LH	Dented	2,805.00 FS	*2,244.00 FS
9	1		*FRONT DOOR OUTER DOOR SEAL - LH	Necessary	166.00 FS	*132.80 FS
10	1		*FRONT DOOR ATTACHMENT PARTS - LH	Not Necessary	157.00 FS	*- FS
11	1		*FRONT DOOR CATCH	Not Necessary	120.00 FS	*- FS
12	1		*FRONT DOOR COVER - LH	Deformed	268.00 FS	*214.40 FS
13	1		*SIDE MIRROR - LH	Cut	2,065.00 FS	*1,652.00 FS
14	1		*SIDE MIRROR CAP - LH	Not Necessary	191.00 FS	*- FS
15	1		*SIDE MIRROR GLASS - LH	Not Necessary	892.00 FS	*- FS
16	1		*REAR DOOR - RH	Dented	2,909.00 FS	*2,327.20 FS
17	1		*REAR DOOR OUTER SEAL	Necessary	135.00 FS	*108.00 FS
18	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	311.00 FS	*- FS
19	1		*REAR DOOR CATCH	Not Necessary	120.00 FS	*- FS
20	1		*REAR DOOR SILL PANEL SEAL	Not Necessary	135.00 FS	*- FS
21	1		*REAR DOOR COVER - LH	Cut	257.00 FS	*205.20 FS
22	2		*FRONT WHEEL COVER - LH / RH	Necessary	536.00 FS	*428.80 FS
23	1		*REAR WHEEL COVER - LH	Cut	268.00 FS	*214.40 FS
24	1		*REAR DOOR TRIM - LH	Not Necessary	179.00 FS	*- FS
25	1		*REAR DOOR HANDLE TRIM	Cut	198.00 FS	*158.00 FS
26	1		*REAR DOOR HANDLE END CAP TRIM - LH	Repair	27.00 FS	*- FS
27	1		*REAR DOOR CORNER TRIM	Not Necessary	46.00 FS	*- FS
28	1		*FRONT NUMBER PLATE	Not Necessary	60.00 FS	*- FS
29	1		*SUNDRIES	Necessary	250.00 FS	*7.68 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 15,552.00 7,692.48

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	800.00	500.00
3	TO RESPRAY FRONT BUMPER, LHS FRONT DOOR, LHS REAR DOOR, LHS WING MIRROR COVER, DOOR HANDLE	New	3,000.00	1,850.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
5	TO DISMANTLE AND RENEW REAR BUMPER, LHS FRONT DOOR AND LHS REAR DOOR. TO REPAIR LHS REAR FENDER AND LHS SILL PANEL. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,000.00	1,500.00
6	TO RESPRAY FRONT BUMPER SPOILER, BOTH FRONT WHEEL ARCH COVER REAR LHS WHEEL ARCH COVER, BOTH LHS DOOR COVER (Supplementary)	New	995.10	600.00
<b>Gross Labour Cost (S\$)</b>			<b>9,467.10</b>	<b>5,122.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >