

[Service Requests](#)[Messages](#)[Claims](#)

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	TPVD Toyota Corolla (SGL1646J)
Date of Loss	21 April 2021
Time of Loss	19:20
Loss Description	SLF1877G (INSD) C/W SGL1646J (TP)
Comment	

Workshop Details

Total Rebate Amount	0
Nett Loss Amount	\$0.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	20



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SGL1646J

Registration State SINGAPORE

Mileage 213134

Purchase Date DD/MM/YYYY



Registration Date * 05/09/2006



Age of Vehicle 14

CATEGORY

POLICY
INFORMATION

ASSESSMENT INFORMATION

Manufacturing
Year

2006

Driver Details

CATEGORY



FNOL INFORMATION

POST SURVEY
INFORMATION


Driver Name

LEE LAI LENG

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Make	TPVD Toyota	<input type="text" value="TOYOTA"/>
Model	Corolla	<input type="text" value="COROLLA ALTIS 1.6 AU"/>
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="MR053ZEC107129355"/>
Engine No		<input type="text" value="3ZZ4597053"/>
Engine Capacity		<input type="text" value="1598"/>
Sum Insured		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Date of Birth	1 January 1999	<input type="text" value="DD/MM/YYYY"/> 
Age	22	
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="DD/MM/YYYY"/> 

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Market Value		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		<input type="text" value="DD/MM/YYYY"/> 
Address	SG, Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="v"/>
Gender	Unknown	<input type="text" value="v"/>
Marital status	Unknown	<input type="text" value="v"/>
Identification #	TBC	<input type="text"/>



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

26/04/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake
(Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

0

Tyre Condition

Age of Tyres

Front Tyre Size

185/70R14

Front left side

YOKOHAMA5mm

Front right side

YOKOHAMA5mm

Spare wheel

Rear Tyre Size

185/70R14

Rear left side

FALKEN7mm

Rear right side

FALKEN7mm



Service Requests

Messages

Claims



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text" value="0"/>	Salvage%	<input type="text" value="0"/>
Discount%	<input type="text" value="25"/>	Settlement%	<input type="text" value="100"/>

Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Cash Loss	<div><div>Yes</div><div>No</div></div>	Part supplied by
Paint Material Ratio	<input type="text" value="80"/>			

A
X
A

Save



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio











Parts & Labour











Miscellaneous










Summary



Parts

Add		Approve		Deny		Submit All								
EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	AC (P)
	0	1		REAR BUMPER	Bent	0	780	No	0	25	0	0	585	R€
	0	1		REAR BUMPER BRACKET RH	Repair	0	0	No	0	0	0	0	0	D€
	0	1		REAR BUMPER BRACKET LH	Repair	0	0	No	0	0	0	0	0	D€
	0	1		REAR BUMPER SIDE RETAINER RH	Damaged	0	68	No	0	25	0	0	51	R€
	0	1		REAR BUMPER SIDE RETAINER LH	Damaged	0	68	No	0	25	0	0	51	R€

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	AC (P)
	0	1		REAR END PANEL	Bent	0	567	No	0	25	0	0	425.25	R€
	0	1		REAR END PANEL INNER GARNISH	Dented	0	165	No	0	25	0	0	123.75	R€
	0	1		TAILLAMP RH	Cracked	0	480	No	0	25	0	0	360	R€
	0	1		TAILLAMP LH	Cracked	0	480	No	0	25	0	0	360	R€
	0	1		TAILLAMP LOWER PANEL RH	Buckled	0	125	No	0	25	0	0	93.75	R€
	0	1		TAILLAMP LOWER PANEL LH	Buckled	0	125	No	0	25	0	0	93.75	R€
	0	1		TAILLAMP INNER PANEL RH	Repair	0	0	No	0	0	0	0	0	D€
	0	1		TAILLAMP INNER PANEL LH	Bent	0	125	No	0	25	0	0	93.75	R€
	0	1		BOOTLID	Buckled	0	580.7	No	0	25	0	0	435.53	R€
	0	1		BOOTLID LAMP RH	Serviceable	0	0	No	0	0	0	0	0	D€

EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	AC (P)
	0	1		BOOTLID LAMP LH	Serviceable	0	0	No	0	0	0	0	0	D€
	0	1		BOOTLID HINGE RH	Repair	0	0	No	0	0	0	0	0	D€
	0	1		BOOTLID HINGE LH	Repair	0	0	No	0	0	0	0	0	D€
	0	1		BOOTLID LOCK	Dented	0	49	No	0	25	0	0	36.75	R€
	0	1		BOOTLID LOCK CATCH	Repair	0	0	No	0	0	0	0	0	D€
	0	1		BOOTLID EMBLEM "1.6"	Necessary	0	38.8	No	0	25	0	0	29.1	R€
	0	1		BOOTLID EMBLEM "E"	Necessary	0	31.5	No	0	25	0	0	23.63	R€
	0	1		BOOTLID EMBLEM "COROLLA"	Necessary	0	47.4	No	0	25	0	0	35.55	R€
	0	1		BOOTLID EMBLEM "VVT-I"	Necessary	0	36.5	No	0	25	0	0	27.38	R€
	0	1		BOOTLID EMBLEM "ALTIS"	Necessary	0	36.1	No	0	25	0	0	27.08	R€

EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	AC (P)
	0	1		BOOTLID LOGO	Necessary	0	38.5	No	0	25	0	0	28.88	R€
	0	1		BOOTLID REFLECTOR LH	Serviceable	0	0	No	0	0	0	0	0	D€
	0	1		BOOTLID REFLECTOR RH	Serviceable	0	0	No	0	0	0	0	0	D€
	0	1		BBOOTLID OUTER CHROME MOULDING	Cracked	0	155.1	No	0	25	0	0	116.33	R€
	0	1		BOOTLID KEY LOCK	Serviceable	0	0	No	0	0	0	0	0	D€
	0	1		SPARE TYRE PANEL	Repair	0	0	No	0	0	0	0	0	D€
	0	1		SPARE TYRE TOP BOARD	Serviceable	0	0	No	0	0	0	0	0	D€
	0	1		REAR FENDER LH	Repair	0	0	No	0	0	0	0	0	D€
	0	1		REAR EXHAUST PIPE	Repair	0	0	No	0	0	0	0	0	D€

EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	AC (P)
	0	1		REAR EXHAUST CENTRE PIPE	Repair	0	0	No	0	0	0	0	0	De
	0	1		REAR EXHAUST CENTRE PIPE MOUNTING	Serviceable	0	0	No	0	0	0	0	0	De













Labour





Add

Approve

Deny

Submit All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREA	0	800	0	0	Reviewing		
	0		SPRAY PAINTING ON ACCIDENT AREA	0	900	0	0	Reviewing		
	0		CHECK WIRING SYSTEM	0	20	0	0	Reviewing		
	0		RESPRAY TUFF KOTE ON AFFECTED AREA	0	60	0	0	Reviewing		
	0		R & R REAR EXHAUST PIPE	0	60	0	0	Reviewing		
	0		R & R CARPET AND INNER TRIM TO ASSIST REPAIR	0	60	0	0	Reviewing		

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		CONDUCT CHASSIS ALIGNMENT	0	0	0	0	Deny		
	0		CONDUCT WHEEL ALIGNMENT	0	0	0	0	Deny		



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition















Taxes & Ratio





Parts & Labour

Miscellaneous

Summary

Add		Approve		Deny		Submit All	
EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	DAYS OF REPAIR : 6 DAYS	Reviewing	0	0		
	0	REAR BUMPER CLIPS	Reviewing	0	50	NECESSARY	
	0	REVERSE SENSOR	Reviewing	0	200	DENTED	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	REAR END PANEL SEALANT	Reviewing	0	30	NECESSARY	
	0	REAR NUMBER PLATE	Deny	0	0	SERVICEABLE	
	0	SPARE TYRE PANEL SEALANT	Deny	0	0	NOT NECESSARY	
	0	SPARE TYRES PANEL INSULATOR	Deny	0	0	NOT NECESSARY	
	0	REAR FENDER CLIPS	Deny	0	0	NOT NECESSARY	
	0	TAIL LAMP PANEL REVIT	Deny	0	0	NOT NECESSARY	
	0	REAR SPORT RIM LH	Deny	0	0	SERVICEABLE	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	REAR TYRE LH	Deny	0	0	SERVICEABLE	
	0	BOOTLID WEATHERSTRIP (\$65.00)(50%)	Reviewing	0	32.5	DENTED	



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$5,209.98
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
Spare Parts		
Labour		
Spare Parts		
Miscellaneous		

Submit for Review



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add		Approve		Deny		Submit All	
EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	FINAL LUMP SUM	Reviewing	0	2000		



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$2,000.00
------------------------	--------	-----------------------	------------

CATEGORY

ESTIMATE

ADJUSTED

Miscellaneous

Submit for Review