



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 555A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BUMPER COVER FRT	BENT	968.78	968.78
1	BUMPER ABSORBER FRT	SERVICEABLE	303.60	-
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	703.14	-
1	BUMPER SPOILER FRT	SERVICEABLE	139.81	-
1	BUMPER FOG LAMP GRILLE RH	SERVICEABLE	159.40	-
1	BUMPER RETAINER FRT LH	SERVICEABLE	116.47	-
1	BUMPER RETAINER FRT RH	DISTORTED	116.47	116.47
1	BUMPER SUPPORT FRT RH	SERVICEABLE	18.37	-
1	BUMPER UNDERTRAY FRT	SERVICEABLE	363.71	-
1	RADIATOR GRILLE	SERVICEABLE	1,313.68	-
1	RADIATOR GRILLE BADGE 'RENAULT'	NOT NECESSARY	173.32	-
1	RADIATOR GRILLE FRAME	SERVICEABLE	1,041.35	-
1	FRAME FULL SUPPORT PANEL	SERVICEABLE	477.37	-
1	LOWER ARM LH	SERVICEABLE	527.51	-
1	KNUCKLE ARM RH	SERVICEABLE	651.53	-
1	ABSORBER FRT RH	SERVICEABLE	277.34	-
1	ABSORBER DUST COVER	SERVICEABLE	175.93	-
1	BONNET	TO REPAIR SEE LABOUR	1,493.56	-
1	WIPER RESERVOIR	SERVICEABLE	173.60	-
1	WIPER RESERVOIR MOTOR	SERVICEABLE	91.78	-
1	HEADLAMP RH	MTG CRACKED	911.10	911.10
1	FENDER PANEL FRT RH	BENT	602.95	602.95
1	FENDER WHEELARCH FRT RH	SERVICEABLE	107.33	-
1	DOOR PANEL FRT RH	TO REPAIR SEE LABOUR	2,188.20	-
1	DOOR SEAL FRT RH	SERVICEABLE	55.30	-
1	DOOR MIRROR RH	SERVICEABLE	1,141.08	-
	LESS 10% DISCOUNT		-1,429.27	-259.93
			12,863.41	2,339.37

Report Ref No. CS/TP21005080/Kqce2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET WHEELARCH CLIP RH (SN)	NOT NECESSARY	66.00	-
1	DOOR STICKER "TRANS-CAB" (SN)	NOT NECESSARY	80.00	-
1	DOOR STICKER "CLASSIC" (SN)	NOT NECESSARY	30.00	-
1	CAP HUB RH FRT (SN)	SERVICEABLE	35.00	-
1	RIM RH FRT (SN)	SERVICEABLE	385.00	-
1	TYRE RH FRT (SN)	SERVICEABLE	330.00	-
			992.00	66.00
<b><u>LABOUR</u></b>				
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM FRT, BONNET AND DOOR PANEL FRT RH.		3,000.00	400.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED.		2,800.00	440.00
	TO CHECK BRAKE EFFICIENCY, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL.	NOT NECESSARY	170.00	-
	TO RUST PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			7,580.00	890.00
<b>GRAND TOTAL</b>			<b>21,435.41</b>	<b>3,295.37</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>3,295.37</b>

Report Ref No. CS/TP21005080/Kqce2

**KONG SENG CHEONG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.