

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 6144L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRT DOOR LH	BENT	2,256.40	2,256.40
1	REAR DOOR LH	TO REPAIR SEE LABOUR	2,201.10	-
1	FRT FENDER LH	BENT	663.00	663.00
	LESS 20% DISCOUNT		-1,024.10	-583.88
			4,096.40	2,335.52
	NETT ITEMS			
1	FRT DOOR COMFORTDELGRO LH (N)	CUT	75.00	75.00
1	REAR DOOR APPS LH (N)	NECESSARY	80.00	80.00
	LESS 10% DISCOUNT		-15.50	-15.50
			139.50	139.50
	<u>LABOUR</u>			
	PANEL BEATING - REAR FENDERS LH ETC. INCLUSIVE OF THE REPAIR OF REAR DOOR LH .		400.00	350.00
	SPRAY PAINT - BOTH BUMPERS ETC.		2,100.00	1,500.00
	TUFF COAT ON AFFECTED PARTS.		160.00	40.00
	TRANSFER OF DOORS.		240.00	60.00
			2,900.00	1,950.00
	GRAND TOTAL		7,135.90	4,425.02
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			3,550.00

Report Ref No. NS/INC21005082/T1tce2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.