

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCV 9001L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	LH/F HEADLAMP (SN)	CRACKED	3,349.33	3,349.33
1	LH/F HEADLAMP CONTROL UNIT (SN)	SERVICEABLE	629.47	-
1	LH/F DISC WHEEL (SN)	SCRATCHED	1,449.01	1,449.01
1	FRT BUMPER (SN)	DEFORMED	1,832.25	1,832.25
1	LH/F BUMPER BRACKET (SN)	NECESSARY	12.88	12.88
1	LH/F BASIC MOUNTING FOR BUMPER (SN)	CUT	84.94	84.94
1	LH/F OUTER PARKING SENSOR (SN)	CUT	182.48	182.48
1	LH/F PARKING SENSOR SEAL (SN)	NECESSARY	6.35	6.35
1	LH/F BOTTOM GARNISH (SN)	SCRATCHED	170.67	170.67
1	LH/F BOTTOM GRILLE (SN)	CRACKED	73.67	73.67
1	LH/F FENDER (SN)	BENT	948.95	948.95
1	LH/F WHEEL ARCH COVER (SN)	SERVICEABLE	130.18	-
1	LH/F BOTTOM GRILLE HOLDER (ADDITIONAL)(SN)	CRACKED	69.42	69.42
1	LH/F CROSS MEMBER BRACKET (ADDITIONAL)(SN)	CRACKED	77.53	77.53
			9,017.13	8,257.48
	<u>LABOUR</u>			
	USE NENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.		380.00	380.00
	CHECK HEADLAMP WITH FOCUS ADJUSTMENT.		120.00	120.00
	INSPECT & CONDUCT WHEEL ALIGNMENT.		540.00	540.00
	REMOVE & REPLACE FRONT BUMPER.FRONT LEFT FENDER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH.		2,400.00	1,440.00
	SUPPLY & TRANSFER 1PC FRONT LEFT RIM PURCHASE ORDER NO.		60.00	60.00
	RESPRAY FRONT BUMPER & FRONT LEFT FENDER.		1,500.00	1,200.00
			5,000.00	3,740.00
	GRAND TOTAL		14,017.13	11,997.48

Report Ref No. CS/SMR21005091/R1uf3n2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS 11,997.48

Report Ref No. CS/SMR21005091/R1uf3n2

MOHAMMED RASUL BIN MOHD YUNUS

**Automotive Assessor** 

P

**ANG BRYAN TANI** 

**Automotive Assessor / Investigator**