



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBH 4469P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
2	FRONT FORK TUBE ASSY	TO REPAIR SEE LABOUR	640.00	-
1	FORK UNDER BRACKET	NOT NECESSARY	185.00	-
1	FRONT WHEEL RIM	TO REPAIR SEE LABOUR	185.00	-
1	FRONT RIM SHAFT	NOT NECESSARY	45.00	-
1	FRONT RIM BEARING	NOT NECESSARY	40.00	-
1	FRONT BRAKE DISC	NOT NECESSARY	155.00	-
1	HEADLAMP	SCRATCHED	185.00	185.00
1	HANDLE BAR	BENT	88.00	88.00
1	HANDLE BAR END (O/S)	SCRATCHED	160.00	30.00
1	SET HAND GRIP	NOT NECESSARY	55.00	-
1	SIDE MIRROR (O/S)	BROKEN	110.00	68.00
1	BRAKE LEVER	SCRATCHED	42.00	42.00
1	SET FAIRING ASSY	CUT	525.00	525.00
1	FRONT FOOTREST BRACKET	BENT	65.00	65.00
2	FRONT FOOTREST RUBBERS	O/S TORN	70.00	30.00
1	BRAKE PEDAL	CUT	45.00	45.00
1	EXHAUST ASSY	TO REPAIR SEE LABOUR	485.00	-
1	EXHAUST PROTECTOR -CHROME	BENT	60.00	60.00
1	EXHAUST PROTECTOR -BLACK	BENT	45.00	45.00
1	REAR FOOTREST BRACKET	NOT NECESSARY	156.00	-
1	REAR FOOTREST	NOT NECESSARY	80.00	-
	LESS 10% DISCOUNT		-342.10	-118.30
			3,078.90	1,064.70
<u>SPECIAL NETT ITEMS</u>				
1	SET NUMBER PLATE (SN)	BENT	28.00	10.00
2	FORK OILS (SN)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN)	NOT NECESSARY	56.00	-
1	SET STEERING CONE (SN)	NECESSARY	90.00	60.00

Report Ref No. CC4/ASM21005092/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BOX (SN)	CUT	380.00	200.00
1	REAR BOX BRACKET (SN)	SERVICEABLE	150.00	-
1	SET STICKER (SN)	NECESSARY	95.00	60.00
			829.00	330.00
	LABOUR			
	TO PROVIDE TOWING SERVICE.		50.00	25.00
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING .	NOT NECESSARY	80.00	-
	TO PROVIDE LABOUR .INCLUSIVE OF THE REPAIR OF FRONT FORK TUBE ASSY,FRONT WHEEL RIM AND EXHAUST ASSY .		400.00	250.00
	TO REPAIR BODY FRAME .	NOT NECESSARY	350.00	-
			880.00	275.00
GRAND TOTAL			4,787.90	1,669.70

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,300.00
---	--	--	-----------------

Report Ref No. CC4/ASM21005092/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.