

ASS. REC. BY:

REF: Asm / 210050931kb

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Cuan 1stn

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: 852k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4-5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 08729

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SIZN 7828 Regn: 03, 09

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or _____

Make: MW E200 Komp c.c. 1796

Colour: M. Grey A/C: Insured / Std / NI / NA

Sp. Reading: 107739 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD 2110 412B 392839

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / A/Rlm or

Tyre Size: F: 225/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 2 mm R/Bal. 3 mm

L/Bal. 2 mm L/Bal. 3 mm

D.O.A. 19/4/21 D.O.I. 26/4/2021

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S 1stn & alc

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>Est not ready</u>
	<u>U Rep B350d Carbur</u>

Date/Time, File Pass to? : Prell. Report : Final Report

Days Of Repair: _____ Resurvey No. of Trip: _____

1) _____
Date/Time, File Return to?

2) _____

Add Fee: : Site Insp (\$) : Interview (\$) : Tech Invs (\$) : Weekend (\$)

Survey Fee:	
Transportation:	
S - RS. SI	
Fees	
Others	
TOTAL	

Report Format : _____
Lump Sum / I.B.I: (\$)

GUAN HIN MOTOR WORKSHOP

NO 10 ANG MO KIO INDUSTRIAL PARK 2A
 #02-03 AMK AUTOPOINT 568047
 Tel No. : 64837111 Fax No. : 64837221
 E-Mail : guanhinmotor@yahoo.com
 Buss. Reg. No. : 06035200X

NOT Authorized
L1 Rmp @ 3500/h
Resurvey After Paint
5 days

AXA INSURANCE PTE LTD
 8 SHENTON WAY
 #24-01 AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department
 Contact : 63387288

Estimate : ES000938

Date : 26/04/2021
 Vehicle Num. : SFN 7828 M
 Make/Model : MERCEDES BENZ E200K-2008
 Chassis/Eng# : WDB2110412B392839/27195631129177
 Accident Date : 19/04/2021
 Claim No. :
 Reference :
 Policy No. : (11/03/2009)

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	FRONT BUMPER <i>1415.20</i>	<i>Bu</i> 1,754.75	✓
2.	1	FRONT BUMPER SPONGE	<i>Sm</i> 86.34	X
3.	1	FRONT BUMPER SPONGE	<i>Sm</i> 86.34	X
4.	1	FRONT BUMPER SPONGE	<i>Sm Net</i> 86.34	X
5.	1	FRONT BUMPER PROTECTOR	<i>Net</i> 62.58	✓
6.	1	FRONT BUMPER PROTECTOR MOULDING	<i>Net</i> 120.68	✓
7.	1	LH FOG LAMP	<i>Sm</i> 342.58	X
8.	1	LH FONG LAMP COVER	<i>Sm</i> 33.95	X
9.	1	LH FOG LAMP CHROME	<i>Sm</i> 121.31	X
10.	1	FRONT LH FENDER	<i>Ry</i> 883.08	✓
11.	1	FRONT LH LOWER ARM	<i>Sm</i> 895.96	X
12.	1	FRONT LH KNUCKLE ARM	<i>BT</i> 569.45	✓
13.	1	FRONT LH SHOCK ABSORBER	<i>Sm</i> 787.25	X
14.	1	LH HEAD LAMP	<i>Sm</i> 2,872.69	X
15.	1	RH SIDE MIRROR SIGNAL LAMP	<i>Sm</i> 135.27	✓
List Total S\$:			<i>105</i>	8,838.57
SPECIAL NETT ITEMS :				
1.	1	SPORT RIM	<i>Net</i> 500.00	✓
Special Nett Total S\$:			500.00	
LABOUR :				
REMOVE & FIX BACK FRONT BUMPER,FENDER, HEAD LAMP,REPAIR,WHEEL HOUSING			700.00	<i>450</i>
REMOVE & FIX BACK LH UNDERCARRIAGE			250.00	<i>80</i>
COMPUTERSE WHEEL ALIGMENT			140.00	<i>60</i>

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

GUAN HIN MOTOR WORKSHOP

NO 10 ANG MO KIO INDUSTRIAL PARK 2A

#02-03 AMK AUTOPOINT 568047

Tel No. : 64837111 Fax No. : 64837221

E-Mail : guanhinmotor@yahoo.com

Buss. Reg. No. : 06035200X

AXA INSURANCE PTE LTD

8 SHENTON WAY

#24-01 AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department

Contact : 63387288

Estimate : ES000938

Date : 26/04/2021

Vehicle Num. : SFN 7828 M

Make/Model : MERCEDES BENZ E200K-2008

Chassis/Eng# : WDB2110412B392839/27195631129177

Accident Date : 19/04/2021

Claim No. :

Reference :

Policy No. : (11/03/2009)

S/N	Quantity	Particular	Unit Price	Amount S\$
		REMOVE & FIX BACK LH SIDE MIRROR SIGNAL SPRAY PAINTING		80.00 900.00
		Labour Total S\$:		2,070.00

201
4401

E. & O.E.

Total S\$: 11,408.57

=====

for GUAN HIN MOTOR WORKSHOP