

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21005109/AVCE2**Date:** 14/09/2021**REFERENCE**

Insured/Claimant:	VISHAL AGARWAL	Policy No:	1900093767	
Date of Loss:	15/04/2021	Nature of Claim:	OD	Claim No: 8300635065SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK9638P		
Make & Model:	AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A)	Engine No:	DAX052277
Reg. Date:	30/04/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF5K2044398
Colour:	White	Odometer:	31524 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$175,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	36,578.00	17,830.32	18,747.68	51.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,872.00	6,872.00	6,000.00	46.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	49,450.00	24,702.32	24,747.68	50.05
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	48,450.00	23,702.32	24,747.68	51.08
+ GST 7.00/7.00% (S\$)	3,391.50	1,659.16	1,732.34	51.08
Nett Amount (S\$)	51,841.50	25,361.48	26,480.02	51.08

INSPECTION

Date of Assignment:	26/04/2021		
Date Inspected:	23/04/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	8.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,567.00 FS	*1,089.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	293.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP - LH	Not Necessary	38.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LH	Cracked	113.00 FS	*90.00 FS
5	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	144.00 FS	*- FS
6	1		*FRONT BUMPER SPOILER	Not Necessary	763.00 FS	*- FS
7	1		*FRONT BUMPER UNDERRUN BAR	Not Necessary	518.00 FS	*- FS
8	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	173.00 FS	*- FS
9	1		*FRONT RADIATOR GRILLE	Cracked	3,530.00 FS	*2,824.00 FS
10	1		*QUATTRO EMBLEM	Necessary	106.00 FS	*84.80 FS
11	1		*FRONT RADIATOR STRIKER PLATE	Cracked	244.00 FS	*194.80 FS
12	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Cracked	581.00 FS	*464.40 FS
13	1		*FRONT BUMPER AIR GUIDE GRILLE END CAP - LH	Cracked	92.00 FS	*73.20 FS
14	2		*FRONT BUMPER LOCKING CLIP	Not Necessary	8.00 FS	-
15	1		*FRONT BUMPER CARRIER	Not Necessary	981.00 FS	*- FS
16	1		*FRONT BUMPER TOP COVER	Cracked	129.00 FS	*102.80 FS
17	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	39.00 FS	*- FS
18	1		*CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
19	1		*AIR CONDITIONER STICKER	Necessary	20.00 FS	*15.52 FS
20	1		*FRONT HORN LOW TONE - LH	Not Necessary	195.00 FS	*- FS
21	1		*FRONT INNER PARKING AID SENSOR	Not Necessary	244.00 FS	*- FS
22	1		*FRONT OUTER PARKING AID SENSOR	Not Necessary	244.00 FS	*- FS
23	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
24	1		*FRONT BONNET	Dented	4,058.00 FS	*3,246.40 FS
25	2		*FRONT BONNET LID HINGE - LH / RH	Not Necessary	322.00 FS	*- FS
26	1		*FRONT BONNET ATTACHMENT PARTS	Not Necessary	141.00 FS	*- FS
27	1		*FRONT BONNET IMPACT PROTECTION - LH / RH / CENTER (3PCS)	Necessary	84.00 FS	*65.68 FS
28	1		*FRONT BONNET STRIKER	Not Necessary	240.00 FS	*- FS
29	2		*FRONT BONNET LOCK	Not Necessary	427.00 FS	*- FS
30	1		*FRONT BONNET BOWDEN CABLE - CENTER	Not Necessary	58.00 FS	*- FS
31	1		*FRONT BONNET RELEASE ELEMENT	Bent	58.00 FS	*46.00 FS
32	1		*FRONT BONNET RELEASE LEVER	Not Necessary	14.00 FS	*- FS
33	1		*HEADLIGHT MOUNTING - LH / RH	N/S Cracked	236.00 FS	*94.40 FS
34	1		*HEADLIGHT - LH / RH	N/S Cracked	16,382.00 FS	*6,552.80 FS
35	1		*HEADLIGHT HOSE	Not Necessary	125.00 FS	*- FS
36	1		*FRONT WHEEL SPOILER - LH	Not Necessary	160.00 FS	*- FS
37	2		*FRONT WHEEL ARCH COVER - LH / RH	Necessary	1,264.00 FS	*1,011.20 FS
38	1		*FRONT RADIATOR AIR GUIDE - LH	Cracked	58.00 FS	*46.32 FS
39	2		*FRONT RADIATOR AIR GUIDE - UPPER / LOWER	Not Necessary	96.00 FS	*- FS
40	1		*FRONT RADIATOR AIR GUIDE - CENTER	Not Necessary	42.00 FS	*- FS
41	1		*FRONT NUMBER PLATE	Necessary	60.00 FS	*60.00 FS
42	1		*SUNDRIES	Necessary	250.00 FS	*22.24 FS
43	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	177.00 FS	*141.60 FS
44	2		*HEADLIGHT LIFT CYLINDER - LH / RH	Not Necessary	280.00 FS	*- FS
45	1		*FRONT LOCK CARRIER (Supplementary)	Cracked	1,400.00 FS	*1,120.00 FS
46	1		*FRONT FENDER BRACE-LH (Supplementary)	Bent	225.00 FS	*179.60 FS
47	1		*COOLANT (Supplementary)	Necessary	269.00 FS	*212.64 FS
48	1		*FRONT FENDER TOP LEDGE COVER-LH OUTER (Supplementary)	Necessary	31.00 FS	*24.64 FS
49	1		*COOLANT HOSE WITH QUICK RELEASE COUPLING (Supplementary)	Damaged	71.00 FS	*56.80 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 36,578.00 17,830.32

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHTS. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BONNET, HINGES AND BOTH FRONT WHEEL ARCH TRIMS	New	4,000.00	1,500.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS. (Supplementary)	New	1,400.00	1,400.00
7	TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION (Supplementary)	New	1,800.00	1,500.00
8	TO REPAIR LHS FRONT FENDER (Supplementary)	New	800.00	-
9	TO RESPRAY LHS FRONT FENDER (Supplementary)	New	1,000.00	550.00
Gross Labour Cost (\$\$)			12,872.00	6,872.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >