

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way, #21-01 SGX Centre 2  
Singapore 068807

**Our File No:** CS/MSG21005111/R1TF3N2**Date:** 02/12/2021**REFERENCE**

Insured/Claimant:	KOH HWEE BOON DORIS	Policy No:	29147606AS2	
Date of Loss:	24/04/2021	Nature of Claim:	OD	Claim No: 635495

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMV9422L</b>	Engine No:	K15B1063232
Make & Model:	SUZUKI JIMNY, 1.5 GLX AT (A)	Chassis No:	JSAGJB74V00137038
Reg. Date:	28/10/2020 (Man. Year: 2020)	Odometer:	18315 km
Colour:	Beige		
Engine Capacity:	1462 cc		
Market Value/New Car Price:	S\$104,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195/80R15	Rear Tyre Size:	195/80
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,313.03	3,357.45	8,955.58	72.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,340.36	2,832.16	3,508.20	55.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>18,653.39</b>	<b>6,189.61</b>	<b>12,463.78</b>	<b>66.82</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>6,219.23</b>		
<b>- Excess (\$\$)</b>	500.00	500.00	0.00	0.00
<b>(\$\$)</b>	18,153.39	5,719.23	12,434.16	68.49
<b>+ GST 7.00/7.00% (\$\$)</b>	1,270.74	400.35	870.39	68.49
<b>Nett Amount (\$\$)</b>	<b>19,424.13</b>	<b>6,119.58</b>	<b>13,304.55</b>	<b>68.49</b>

**INSPECTION**

Date of Assignment:	26/04/2021	
Date Inspected:	26/04/2021	Inspected At: Champion Motors (1975) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462
Estimated Period of Repair:	7.0 days	

**Adjuster:** MOHD RASUL**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 02 Dec 2021)
<b>Parts:</b>	192	SUZUKI JIMNY 1.5 GLX AT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMV9422L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*NUMBER PLATE	Bent	80.00 FS	*80.00 FS
2	1		*HEADLAMP ASSY,R	Cracked	887.25 FS	*887.25 FS
3	1		*HEADLAMP ASSY,L	Serviceable	887.25 FS	*- FS
4	2		*LAMP ASSY,FOG AND DRL	Serviceable	309.38 FS	*- FS
5	1		*BRACKET,FOG LAMP,R	Serviceable	25.91 FS	*- FS
6	1		*BRACKET,FOG LAMP,L	Serviceable	25.91 FS	*- FS
7	2		*ARM ASSY,FR LEADING	Serviceable	569.24 FS	*- FS
8	1		*ROD ASSY,FR LATERAL	Serviceable	72.64 FS	*- FS
9	2		*ABSORBER,FR SHOCK	Serviceable	285.82 FS	*- FS
10	1		*BAR,FR STABILIZER	Serviceable	146.85 FS	*- FS
11	1		*KNUCKLE,STRG,R	Serviceable	235.57 FS	*- FS
12	1		*KNUCKLE,STRG,L	Serviceable	257.17 FS	*- FS
13	1		*JOINT ASSY,FR AXLE SHAFT,R	Serviceable	471.11 FS	*- FS
14	1		*JOINT ASSY,FR AXLE SHAFT,L	Serviceable	471.11 FS	*- FS
15	2		*HUB SET,FR WHL	Serviceable	245.78 FS	*- FS
16	1		*SPINDLE,FR WHEEL,R	Serviceable	171.56 FS	*- FS
17	1		*SPINDLE,FR WHEEL,L	Serviceable	171.56 FS	*- FS
18	2		*BEARING,FR WHEEL	Serviceable	186.90 FS	*- FS
19	2		*HUB ASSY,AIR LOCKING	Serviceable	738.08 FS	*- FS
20	1		*HOUSING,FR AXLE	Serviceable	914.74 FS	*- FS
21	1		*WHEEL,AL (15X5 1/2J) (3 Pcs)	Scratched (2 Pcs only)	1,224.90 FS	*816.60 FS
22	1		*BOX ASSY,STRG GEAR	Serviceable	1,048.24 FS	*- FS
23	1		*ROD,STRG DRAG	Serviceable	94.65 FS	*- FS
24	1		*END ROD	Serviceable	116.21 FS	*- FS
25	1		*END ROD	Serviceable	47.14 FS	*- FS
26	1		*END ROD,STRG	Serviceable	125.25 FS	*- FS
27	1		*END ROD	Serviceable	47.14 FS	*- FS
28	1		*END ROD	Serviceable	47.14 FS	*- FS
29	1		*MEMBER,COMP 1ST MOUNT	Serviceable	39.26 FS	*- FS
30	1		*PANEL COMP,1ST MOUNT,R	Serviceable	70.69 FS	*- FS
31	1		*BRACKER,FR OUTER PANEL LWR,L	Serviceable	2.77 FS	*- FS
32	1		*BRACKER,FR OUTER PANEL UPR,R	Serviceable	5.92 FS	*- FS
33	1		*PANEL,FR OUTER	Bent	361.20 FS	*361.20 FS
34	1		*COVER,FRONT PANEL UPR	Serviceable	7.46 FS	*- FS
35	1		*SHROUD RADIATOR UPR	Serviceable	43.20 FS	*- FS
36	1		*PROTECTOR,FRONT PANEL LWR,R	Serviceable	5.92 FS	*- FS
37	1		*PROTECTOR,FRONT PANEL LWR,L	Serviceable	5.92 FS	*- FS
38	10		*CLIP	Necessary	15.40 FS	*15.40 FS
39	1		*PANEL,FR FENDER,R	Bent	102.07 FS	*102.07 FS
40	1		*LINING COMP,FRONT FENDER,R	Torn	35.36 FS	*35.36 FS
41	1		*HOLDER,COWL SIDE	Serviceable	3.15 FS	*- FS
42	10		*CLIP	Necessary	15.40 FS	*15.40 FS
43	1		*BUMPER,FRONT	Deformed	321.94 FS	*321.94 FS
44	1		*GARNISH,FR BPR LICENSE (BLACK)	Serviceable	28.27 FS	*- FS
45	1		*NET,FRONT BUMPER	Serviceable	24.75 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*SKIRT,FR AIR DAM	Serviceable	18.86 FS	*- FS
47	1		*GRILLE COMP,RADIATOR	Cracked	223.80 FS	*223.80 FS
48	1		*GUARD,FR FNDR SPLASH,R (BLACK)	Scratched	76.57 FS	*76.57 FS
49	1		*PROTECTOR,FR FENDER SPLASH	Necessary	14.55 FS	*14.55 FS
50	9		*CLIP	Necessary	12.00 FS	*10.80 FS
51	1		*GUARD,FR FNDR SPLASH,L (BLACK)	Serviceable	76.57 FS	*- FS
52	1		*PROTECTOR,FR FENDER SPLASH	Serviceable	14.55 FS	*- FS
53	1		*GUARD,RR FNDR SPLASH,R (BLACK)	Scratched	80.51 FS	*80.51 FS
54	1		*PROTECTOR,RR FENDER SPLASH	Not Necessary	14.92 FS	*- FS
55	10		*CLIP	Not Necessary	13.50 FS	*- FS
56	1		*GUARD ASSY,SIDE SILL SPLASH R	Serviceable	82.46 FS	*- FS
57	1		*PROTECTOR,SIDE SILL SPLASH	Serviceable	10.24 FS	*- FS
58	1		*MIRROR ASSY,RR VIEW R (BLACK)	Serviceable	177.86 FS	*- FS
59	1		*SUNDRIES	Necessary	50.00 FS	*50.00 FS
60	1		*LH FRONT TYRE (70%)	Cut	380.00 FS	*266.00 FS
61	1		*BRACKER,FR OUTER PANEL LWR,R	Serviceable	2.77 FS	*- FS
62	1		*PANEL COMP,1ST MOUNT,L	Serviceable	70.69 FS	*- FS

F=Franchise part. S=SpcNett.

<b>Total Parts (\$\$)</b>	<b>12,313.03</b>	<b>3,357.45</b>
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CHECK WIRING AND CONDUCT WATER TEST	New	89.66	89.66
2	TO CONDUCT FULL WHEEL ALIGNMENT	New	131.85	131.85
3	TO CONDUCT ADJUSTMENT ON FRONT RADAR SENSOR	New	131.85	131.85
4	REPLACE RIM AND WHEEL BALANCING	New	117.20	117.20
5	REPLACE FRONT UNDERCARRIAGE	New	1,054.80	0.00
6	REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS	New	2,637.00	1,054.80
7	RESPRAY ACC AFFECTED AREAS	New	2,178.00	1,306.80
<b>Gross Labour Cost (S\$)</b>			<b>6,340.36</b>	<b>2,832.16</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >