

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE I	PTE LTD		Ref:	CC4/ASM21005124/Tpa3q2	
	8 SHENTON WAY AXA TOWERSING			Date:	17/05/2022	
	ATTN:VALE OH			Code:	ASM	
1.	. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	XE 4828S	Veh. Inspected		SLH 9698T	
	Policy No.	GA540761	Coverage (\$)		0.00	
	Claim No.	S1M033GY	Excess (\$)		0.00	
	Assign From		Assign Date		26/04/2021	
2. Vehicle Particulars & Condition						
	Make & Model	VOLKSWAGEN JETTA	c.c		1390	
	Engine No.	HIDDEN	Year of Reg.		2011	
	Chassis No.	WVWZZZ16ZCM002894	Colour		WHITE	
	Odometer	203404 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	225/45 R18	YOKOHAMA		6 mm	
	L/H Front Tyre	225/45 R18	YOKOHAMA		6 mm	
	R/H Rear Tyre	225/45 R18	YOKOHAMA		6 mm	
	L/H Rear Tyre	225/45 R18	YOKOHAMA		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	17/02/2021	Inspection Dat	е	27/04/2021	
	Survey held at	RICO 60 AUTO SERVICES PTE	LTD			
		8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875				
5a.	a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	STIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				