

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1195D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRT BUMPER	TO REPAIR SEE LABOUR	430.90	-
1	FRT FENDER LH	BENT	588.80	588.80
1	FRT FENDER (BLUE-DRIVE) LH	NECESSARY	26.60	26.60
1	FRT WHEEL CAP LH	CUT	346.40	346.40
	LESS 20% DISCOUNT		-278.54	-192.36
			1,114.16	769.44
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRT BUMPER.		400.00	350.00
	SPRAY PAINTING.		600.00	500.00
	TUFF KOTE.		40.00	30.00
			1,040.00	880.00
	GRAND TOTAL		2,154.16	1,649.44

RECOMMENDED COST OF REPAIRS (CONFIRMED)		1,649.44

Report Ref No. NS/INC21005130/T1qcn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.