

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJC 2464Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER (CONSISTENT)	CRACKED	652.30	652.30
1	FRONT BUMPER FOG LAMP -LH (CONSISTENT)	SERVICEABLE	264.80	-
1	FRONT BUMPER FOG LAMP COVER -LH (CONSISTENT)	SERVICEABLE	65.70	-
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	TO REPAIR SEE LABOUR	246.10	-
2	FRONT BUMPER SIDE RETAINER @\$28.50 (CONSISTENT)	N/S DISTORTED	57.00	28.50
1	FRONT BUMPER TOP BEAM (CONSISTENT)	CRACKED	95.30	95.30
1	FRONT RADIATOR GRILLE (CONSISTENT)	SERVICEABLE	322.50	-
1	FRONT RADIATOR TOP PLATE (CONSISTENT)	SERVICEABLE	812.10	-
1	FRONT RADIATOR LOGO (CONSISTENT)	SERVICEABLE	32.90	-
1	FRONT HEAD LAMP (AUTO) -LH (CONSISTENT)	CRACKED	576.40	576.40
1	FRONT HEAD LAMP BRACKET (CONSISTENT)	CRACKED	65.70	65.70
	LESS 20% DISCOUNT		-638.16	-283.64
			2,552.64	1,134.56
	SPECIAL NETT ITEMS			
10	REAR BUMPER CLIP @\$5.00 (SN) (CONSISTENT)	NECESSARY	50.00	50.00
5	FRONT RADIATOR GRILLE CLIP @\$5.00(SN) (CONSISTENT)	NOT NECESSARY	25.00	-
			75.00	50.00
	<u>LABOUR</u>			
	TO CHECK WIRING .		50.00	20.00
	TO PANEL BEATING ,REMOVING & REPLACING OF NEW PARTS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT .		800.00	400.00
	TO SPRAY PAINTING ON AFFECTED AREA.		600.00	400.00
			1,450.00	820.00
	GRAND TOTAL		4,077.64	2,004.56



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,600.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM21005132/Kgs3q2

KONG SENG CHEONG

Licensed Appraiser