

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21005134/KRA3Q2**Date:** 14/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100420381
Claimant Vehicle No :	SLM1371L	Insured Vehicle No :	SKT9367Y
Date of Loss:	22/04/2021	Nature of Claim:	TP
		Claim No:	7192933539SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM1371L		
Make & Model:	SUBARU FORESTER, 2.0 XT CVT AWD SR (A)	Engine No:	FA20B923980
Reg. Date:	22/03/2017 (Man. Year: 2016)	Chassis No:	JF1SJGK85HG084640
Colour:	Metallic Pearl White	Odometer:	55926 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Dunlop 8 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 8 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,593.00	14,424.20	5,168.80	26.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	2,320.00	880.00	27.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,793.00	16,744.20	6,048.80	26.54
Approved Total (Overridden) (S\$)		15,100.00		
(S\$)	22,793.00	15,100.00	7,693.00	33.75
+ GST 7.00/7.00% (S\$)	1,595.51	1,057.00	538.51	33.75
Nett Amount (S\$)	24,388.51	16,157.00	8,231.51	33.75
+ Car Rental (27.0 x S\$100.00/day) (S\$)		2,700.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		18,859.00		

INSPECTION

Date of Assignment:	26/04/2021	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint Singapore 568047
Date Inspected:	26/04/2021 Inspected At:	
Estimated Period of Repair:	24.0 days	

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Buckled	882.00 FL	*882.00 FL
2	2		*FRONT BONNET HINGE LH/RH	Repair	96.00 FL	*- FL
3	2		*FRONT BONNET INSULATOR LH/RH	Deformed	80.00 FL	*80.00 FL
4	20		*FRONT BONNET CLIPS	Necessary	70.00 FL	*70.00 FL
5	1		*FRONT BONNET AIR DUCT BIG	Cracked	56.00 FL	*56.00 FL
6	1		*FRONT BONNET AIR DUCT SMALL	Cracked	12.00 FL	*12.00 FL
7	1		*FRONT BONNET INNER LOCK	Distorted	60.00 FL	*60.00 FL
8	1		*FRONT BONNET CATCH	Distorted	40.00 FL	*40.00 FL
9	1		*FRONT BONNET GRILLE (TOP)	Cracked	208.00 FL	*208.00 FL
10	1		*FRONT BONNET EMBLEM	Necessary	67.60 FL	*67.60 FL
11	1		*FRONT BONNET BRACKET	Serviceable	15.00 FL	*- FL
12	2		*HEADLAMP LH/RH	Broken	4,760.00 FL	*4,760.00 FL
13	2		*HEADLAMP LOWER BEAM LH /RH 2	Distorted	80.00 FL	*80.00 FL
14	1		*HEADLAMP WASHER NOZZLE LH/RH	O/S Cracked	158.40 FL	*79.20 FL
15	1		*HEADLAMP WASHER NOZZLE COVER LH/RH	O/S Missing	108.00 FL	*54.00 FL
16	1		*HEADLAMP WASHER NOZZLE PIPE	Serviceable	64.80 FL	*- FL
17	1		*FRONT GRILLE (LOWER)	Cracked	316.80 FL	*316.80 FL
18	8		*FRONT GRILLE CLIPS	Necessary	28.00 FL	*28.00 FL
19	1		*FRONT BUMPER	Buckled	594.50 FL	*594.50 FL
20	2		*FRONT BUMPER SIDE RETAINER LH/RH	Distorted	25.20 FL	*25.20 FL
21	15		*FRONT BUMPER CLIPS	Necessary	52.50 FL	*52.50 FL
22	1		*TOWING COVER	Dented	6.00 FL	*6.00 FL
23	1		*FRONT BUMPER REINFORCEMENT	Bent	288.00 FL	*288.00 FL
24	1		*FRONT BUMPER SPONGE	Bent	126.00 FL	*126.00 FL
25	2		*FOGLAMP LH/RH	Serviceable	544.00 FL	*- FL
26	2		*FOGLAMP COVER CHROME LH/RH	Serviceable	96.00 FL	*- FL
27	2		*FRONT FENDER LH/RH	Buckled	600.00 FL	*600.00 FL
28	2		*FRONT FENDER COWLING LH/RH	Serviceable	192.00 FL	*- FL
29	16		*FRONT FENDER COWLING CLIPS	Not Necessary	56.00 FL	*- FL
30	1		*RADIATOR SUPPORT PANEL ASSY	Bent	400.00 FL	*400.00 FL
31	1		*RADIATOR SUPPORT PANEL TOP GARNISH	Cracked	24.00 FL	*24.00 FL
32	8		*RADIATOR SUPPORT PANEL TOP GARNISH CLIPS	Necessary	28.00 FL	*28.00 FL
33	1		*OIL COOLER	Serviceable	238.00 FL	*- FL
34	1		*OIL COOLER BRACKET (NPA)	Repair	0.00 FL	*- FL
35	1		*OIL COOLER INLET HOSE	Serviceable	19.50 FL	*- FL
36	1		*OIL COOLER OUTLET HOSE	Serviceable	29.50 FL	*- FL
37	1		*AIR CON CONDENSER	Bent	680.00 FL	*680.00 FL
38	1		*AIR CON CONDENSER FAN MOTOR ASSY	Cracked	520.00 FL	*520.00 FL
39	1		*AIR CON CONDENSER PIPE (FROM COND TOP COMP)	Serviceable	180.00 FL	*- FL
40	1		*AIR CON CONDENSER PIPE (FRPOM COND TO VALVE)	Serviceable	180.00 FL	*- FL
41	1		*RADIATOR	Bent / Punctured	900.00 FL	*900.00 FL
42	1		*RADIATOR FAN MOTOR	Dented	324.00 FL	*324.00 FL
43	1		*RADIATOR FAN BLADE	Cracked	60.00 FL	*60.00 FL
44	1		*RADIATOR FAN COWLING	Cracked	96.00 FL	*96.00 FL
45	1		*RADIATOR SPARE TANK	Dented	72.00 FL	*72.00 FL
46	1		*RADIATOR TOP HOSE	Cut	44.00 FL	*44.00 FL
47	1		*RADIATOR BOTTOM HOSE	Serviceable	32.00 FL	*- FL
48	2		*RADIATOR TOP BRACKET LH/RH	Repair	32.80 FL	*- FL
49	2		*RADIATOR AIR GUIDE LH/RH	Serviceable	37.40 FL	*- FL
50	1		*WASHER TANK	Serviceable	104.00 FL	*- FL
51	1		*TURBO INLET HOSE RH	Serviceable	204.00 FL	*- FL
52	1		*FAN BELT	Serviceable	65.00 FL	*- FL
53	1		*IDLER BEARING	Serviceable	72.00 FL	*- FL
54	1		*FRONT ENGINE MOUNTING RH	Serviceable	220.00 FL	*- FL
55	1		*FRONT ENGINE MOUNTING LH	Serviceable	220.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*GEARBOX MOUNTING REAR	Serviceable	120.00 FL	*- FL
57	1		*ENGINE UNDER COVER FRONT	Repair	320.00 FL	*- FL
58	10		*ENGINE UNDER COVER CLIPS	Not Necessary	35.00 FL	*- FL
59	1		*AIR DUCT OUTER	Serviceable	56.00 FL	*- FL
60	2		*AIR DUCT CLIPS	Not Necessary	7.00 FL	*- FL
61	1		*AIR FILTER BOX HOUSING FRT	Serviceable	36.00 FL	*- FL
62	1		*AIR FILTER HOUSING REAR	Serviceable	36.00 FL	*- FL
63	2		*HORN	Serviceable	115.60 FL	*- FL
64	1		*TAILGATE EMBLEM	Necessary	88.00 FL	*88.00 FL
65	1		*TAILGATE SUBARU FORESTER LOGO	Necessary	72.00 FL	*72.00 FL
66	1		*TAILGATE XT LOGO	Necessary	72.00 FL	*72.00 FL
67	1		*TAILGATE INNER LOCK	Repair	560.00 FL	*- FL
68	2		*TAILLAMP LH/RH	Serviceable	864.00 FL	*- FL
69	1		*REAR BUMPER	Buckled / Cracked	540.00 FL	*540.00 FL
70	2		*REAR BUMPER SIDE RETAINER LH/RH	Serviceable	32.00 FL	*- FL
71	15		*REAR BUMPER CLIPS	Necessary	52.50 FL	*52.50 FL
72	1		*REAR BUMPER TOW COVER	Missing	14.00 FL	*14.00 FL
73	2		*REAR BUMPER REFLECTOR LH/RH	Serviceable	45.60 FL	*- FL
74	1		*REAR BUMPER REINFORCEMENT	Bent	320.00 FL	*320.00 FL
75	1		*REAR END PANEL	Bent	288.00 FL	*288.00 FL
76	1		*REAR END PANEL TOP GARNISH	Serviceable	40.00 FL	*- FL
77	1		*KEYLESS ANTENNA	Serviceable	95.00 FL	*- FL
78	1		*COMPARTMENT SPONGE CENTER	Cracked	120.00 FL	*120.00 FL
79	1		*COMPARTMENT SPONGE LH & RH	N/S Cracked	64.80 FL	*32.40 FL
80	1		*SPARE TYRE PANEL	Bent	432.00 FL	*432.00 FL
81	1		*SPARE TYRE PANEL TOP TRIM BOARD	Serviceable	320.00 FL	*- FL
82	1		*SPARE TYRE SPONGE TOP	Cracked	36.00 FL	*36.00 FL
83	1		*SPARE TYRE SPONGE LOWER	Cracked	100.00 FL	*100.00 FL
84	1		*TOOL BOX SPONGE (NPA)	Serviceable	0.00 FL	*- FL
85	1		*SPARE TYRE HOLDER	Repair	10.10 FL	*- FL
86	1		*SPARE TYRE HOLDER SCREW	Serviceable	15.10 FL	*- FL
87	1		*REAR EXHAUST ASSY RH	Bent	668.00 FL	*668.00 FL
88	2		*REAR EXHAUST BUSH	Serviceable	24.00 FL	*- FL
89	1		*REAR EXHAUST GASKET	Not Necessary	8.00 FL	*- FL
90	2		*REAR CHASSIS LH/RH	Repair	708.00 FL	*- FL
91	1		*SET REVERSE SENSOR	Dented	200.00 FS	*200.00 FS
92	1		*NUMBER PLATE	Bent	35.00 FS	*35.00 FS
93	1		*RADIATOR COOLANT	Necessary	30.00 FS	*30.00 FS
94	1		*ATF OIL	Necessary	180.00 FS	*60.00 FS
95	1		*FRONT BONNET CHROME UPPER	Dented	150.40 FL	*150.40 FL
96	1		*DUCT -BUMPER	Dented	16.00 FL	*16.00 FL
97	1		*RADIATOR SPONGE	Cracked	19.50 FL	*19.50 FL
98	1		*PACKING RADIATOR	Necessary	28.70 FL	*28.70 FL
99	1		*PACKING RADIATOR LH	Necessary	28.70 FL	*28.70 FL
100	1		*FRONT LOWER MEMBER	Bent	120.00 FL	*120.00 FL
101	1		*SILENVER LH	Bent	668.00 FL	*668.00 FL
102	1		*STAY HOOD SUPPORT	Bent	110.00 FL	*110.00 FL
103	1		*REAR CENTRE SILENCER PIPE	Bent	1,100.00 FL	*1,100.00 FL
104	1		*REAR FRAME SUB ASSEMBLY	Buckled	760.00 FL	*760.00 FL
105	1		*REAR CROSSMEMBER	Bent	154.00 FL	*154.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	24,380.00	17,949.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	4,787.00	3,524.80
Total Parts (\$\$)	19,593.00	14,424.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC .TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	40.00
2	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES ,RADIATOR AND HOSES ,VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS	New	100.00	100.00
3	TO REMOVE/REINSTALL ENGINE MOUNTING & GEARBOX MOUNTING	New	120.00	0.00
4	TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT	New	280.00	120.00
5	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	60.00
6	TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD RADIATOR SUPPORT PANEL,TO KNOCK & REPAIR FRONT CHASSIS LH/RH,FRONT DOOR LH/RH INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	1,200.00	800.00
7	TO SPRAY BONNET ,FRONT BUMPER ,FRONT FENDER LH/RH ,RADIATOR SUPPORT PANEL ,FRONT CHASSIS LH /RH ,FRONT DOOR LH/RH	New	1,400.00	1,200.00
Gross Labour Cost (\$\$)			3,200.00	2,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >