

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/GRB21005135/UBS3Q2  
**Date:** 03/06/2021**REFERENCE**

|                              |                                       |                             |                 |
|------------------------------|---------------------------------------|-----------------------------|-----------------|
| Handling Insurer:            | India International Insurance Pte Ltd | Policy No:                  | D21MFL0000447   |
| <b>Claimant Vehicle No :</b> | SLD463J                               | <b>Insured Vehicle No :</b> | SLM5591S        |
| Date of Loss:                | 24/04/2021                            | Nature of Claim:            | TP              |
|                              |                                       | Claim No:                   | MFL2021D0001802 |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                     |             |                   |
|-----------------------------|-------------------------------------|-------------|-------------------|
| Reg No:                     | <b>SLD463J</b>                      |             |                   |
| Make & Model:               | MAZDA 3, 1.4 SEDAN 1.5L SP.6EAT (A) | Engine No:  | P520354691        |
| Reg. Date:                  | 31/05/2016 (Man. Year: 2016)        | Chassis No: | JM6BM42A8G0336446 |
| Colour:                     | Grey                                | Odometer:   | 81107 km          |
| Engine Capacity:            | 1496 cc                             |             |                   |
| Market Value/New Car Price: | N/A                                 |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>   |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

**CONDITION OF TYRES**

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 205/60 R16   | Rear Tyre Size:  | 205/60 R16   |
| Front Left Side:  | Hankook 6 mm | Rear Left Side:  | Hankook 6 mm |
| Front Right Side: | Hankook 6 mm | Rear Right Side: | Hankook 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 7,736.26          | 4,219.60          | 3,516.66          | 45.46         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 5,860.00          | 1,070.00          | 4,790.00          | 81.74         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>13,596.26</b>  | <b>5,289.60</b>   | <b>8,306.66</b>   | <b>61.10</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>4,200.00</b>   |                   |               |

|                                    |                  |                 |                 |              |
|------------------------------------|------------------|-----------------|-----------------|--------------|
| <b>Nett Amount (S\$)</b>           | <b>13,596.26</b> | <b>4,200.00</b> | <b>9,396.26</b> | <b>69.11</b> |
| <b>Global Sum Settlement (S\$)</b> |                  | <b>0.00</b>     |                 |              |

INSPECTION

Date of Assignment: 26/04/2021

Date Inspected: 27/04/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Euro Success Services Pte Ltd (HQ)  
 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY  
 Singapore 417883

**Adjuster:** MARCUS CHUA**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                      |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 25 May 2021)                        |
| <b>Parts:</b>        | 143                                                                                                                                                                          | MAZDA 3 1.4 SEDAN 1.5L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                    |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SLD463J)                                                                                                                                     |                                                                      |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                      |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                      |

### Recommended Parts

| No. | Qty | Part No. | Particulars                       | Condition       | Repairer's  | Amount       |
|-----|-----|----------|-----------------------------------|-----------------|-------------|--------------|
| 1   | 1   |          | *BONNET                           | Deformed / Bent | 1,125.80 FL | *1,022.20 FL |
| 2   | 1   |          | *FRONT BUMPER                     | Distorted       | 1,500.00 FL | *1,083.30 FL |
| 3   | 1   |          | *FRONT BUMPER SIDE RETAINER       | N/S Cracked     | 91.00 FL    | *22.50 FL    |
| 4   | 1   |          | *FRONT BUMPER FOGLAMP LH          | Not Necessary   | 155.60 FL   | *- FL        |
| 5   | 1   |          | *FRONT BUMPER FOGLAMP COVER LH    | Not Necessary   | 111.20 FL   | *- FL        |
| 6   | 1   |          | *FRONT BUMPER LOWER COVER         | Not Necessary   | 55.20 FL    | *- FL        |
| 7   | 1   |          | *HEADLAMP LED LH                  | Cracked         | 2,515.20 FL | *2,100.20 FL |
| 8   | 1   |          | *HEADLAMP LOWER BRACKET LH        | Not Necessary   | 180.45 FL   | *- FL        |
| 9   | 1   |          | *FRONT FENDER LH                  | Dented          | 385.50 FL   | *385.50 FL   |
| 10  | 1   |          | *FRONT FENDER INNER COWLING LH    | Torn            | 145.80 FL   | *145.80 FL   |
| 11  | 1   |          | *FRONT SHOCK ABSORBER LH          | Not Necessary   | 320.25 FL   | *- FL        |
| 12  | 1   |          | *FRONT KNUCKLE ARM LH             | Not Necessary   | 438.60 FL   | *- FL        |
| 13  | 1   |          | *FRONT KNUCKLE ARM BEARING LH     | Not Necessary   | 435.80 FL   | *- FL        |
| 14  | 1   |          | *FRONT LOWER ARM LH               | Not Necessary   | 260.26 FL   | *- FL        |
| 15  | 1   |          | *FRONT WHEEL BEARING              | Not Necessary   | 430.00 FL   | *- FL        |
| 16  | 1   |          | *SET FRONT BUMPER CLIPS           | Necessary       | 55.20 FS    | *40.00 FS    |
| 17  | 1   |          | *FRONT BUMPER LOWER SPOILER       | Not Necessary   | 180.20 FS   | *- FS        |
| 18  | 1   |          | *FRONT SPORT RIM LH               | Not Necessary   | 300.00 FS   | *- FS        |
| 19  | 1   |          | *FRONT TYRE LH                    | Not Necessary   | 108.08 FS   | *- FS        |
| 20  | 1   |          | *FRONT FENDER INNER COWLING CLIPS | Not Necessary   | 45.00 FS    | *- FS        |
| 21  | 1   |          | *FRONT FENDER WHEEL ARCH CLIPS    | Not Necessary   | 58.25 FS    | *- FS        |
| 22  | 1   |          | *FRONT FENDER SEALANT LH          | Not Necessary   | 45.00 FS    | *- FS        |
| 23  | 1   |          | *FRONT BUMPER LOWER COVER CLIPS   | Not Necessary   | 52.00 FS    | *- FS        |
| 24  | 1   |          | *FRONT DOOR MIRROR ASSY N/S       | Damaged         | 465.00 FL   | *465.00 FL   |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                 |                 |
|------------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>9,459.39</b> | <b>5,264.50</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b> | 1,723.13        | 1,044.90        |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's               | Amount          |
|-----|-----|----------|-------------|-----------|--------------------------|-----------------|
|     |     |          |             |           | <b>Total Parts (S\$)</b> | <b>7,736.26</b> |
|     |     |          |             |           |                          | <b>4,219.60</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                      | Lab.Type | Repairer's      | Amount          |
|--------------------------------|--------------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>     |                                                  |          |                 |                 |
| 1                              | PANEL BEATING ON AFFECTED AREAS                  | New      | 1,350.00        | 300.00          |
| 2                              | SPRAY PAINTING ON AFFECTED AREAS                 | New      | 1,250.00        | 700.00          |
| 3                              | TO CHECK ELECTRICAL WIRING /RESET TROUBLE CODE } | New      | 350.00          | 20.00           |
| 4                              | REALIGN HEADLAMP }                               | New      | 180.00          | 0.00            |
| 5                              | REMOVE AND REFIR FRONT UNDERCARRIAGE             | New      | 200.00          | 0.00            |
| 6                              | CONDUCT FULL WHEEL ALIGNMENT                     | New      | 80.00           | 0.00            |
| 7                              | TO RESPRAY UNDERCOATING                          | New      | 250.00          | 50.00           |
| 8                              | APPLY ANTI RUST ON AFFECTED AREAS                | New      | 2,200.00        | 0.00            |
| <b>Gross Labour Cost (S\$)</b> |                                                  |          | <b>5,860.00</b> | <b>1,070.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >