

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21005141/GPS3Q2
Date: 06/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800102252
Claimant Vehicle No :	XD6306Z	Insured Vehicle No :	SKA3828Z
Date of Loss:	24/04/2021	Nature of Claim:	TP
		Claim No:	8092936131SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XD6306Z	Engine No:	50532841603286
Make & Model:	MAN TGS 18.320, 10.5 D 4X2 BLS (M)	Chassis No:	WMA49SZZ9DM608279
Reg. Date:	30/10/2012 (Man. Year: 2012)	Odometer:	1317669 km
Colour:	Green		
Engine Capacity:	10518 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5 (D)	Rear Tyre Size:	295/80 R22.5 (D)
Front Left Side:	Falken 6/6 mm	Rear Left Side:	Falken 6/6 mm
Front Right Side:	Falken 6/6 mm	Rear Right Side:	Falken 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,498.00	1,631.20	866.80	34.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	700.00	370.00	330.00	47.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,198.00	2,001.20	1,196.80	37.42
Approved Total (Overridden) (S\$)		1,600.00		

(S\$)	3,198.00	1,600.00	1,598.00	49.97
+ GST 7.00/7.00% (S\$)	223.86	112.00	111.86	49.97
Nett Amount (S\$)	3,421.86	1,712.00	1,709.86	49.97
+ Loss of Use (2.0 x S\$200.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,114.00		
Global Sum Settlement (S\$)		2,100.00		

INSPECTION

Date of Assignment: 26/04/2021

Date Inspected: 28/04/2021

Estimated Period of Repair: 2.0 days

Inspected At: Connect3 (woodlands) (HQ)
566 Woodlands Road
Singapore 728697

Adjuster: XING GUO QIANG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FOOT STEP PLATE LH	Cut	185.00 F	*125.45 FL
2	1		*FOOT STEP PLATE BRACKET LH	Repair	355.00 F	*- FL
3	1		*FOOT STEP HOUSING LH	Cracked	750.00 F	*750.00 FL
4	1		*FRONT LH HEADLAMP HOUSING	Cut	760.00 F	*626.28 FL
5	1		*FRONT LH SIDE GARNISH (BEHIND HEADLAMP HOUSING)	Cut	345.00 F	*255.36 FL
6	1		*LH SIDE SMALL LAMP	Cracked	103.00 F	*55.35 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,498.00	1,812.44
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	181.24
Total Parts (S\$)	2,498.00	1,631.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIT FRONT SENSORS	New	80.00	0.00
2	CHECK WIRING	New	20.00	20.00
3	LABOUR CHARGES	New	600.00	350.00
Gross Labour Cost (\$\$)			700.00	370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >