6/15/2021 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/AIG21005145/NPA3Q2

Date:

15/06/2021

REFERENCE

Date of Loss:

Handling Insurer: Claimant Vehicle No: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Nature of Claim:

Insured Vehicle No:

ΤP

SGS631X

Engine No:

Chassis No:

Odometer:

Claim No:

0023665498SG

KMHC851CVKU107532

G4LEJU081776

309007 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC2639J

SHC2639J

26/04/2021

Make & Model: HYUNDAI AE IONIQ HEV DCT, 1.6 (A)

Reg. Date: 06/09/2018 (Man. Year: 2018)

Colour: Blue

Engine Capacity: 1580 cc Market Value/New Car Price: N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Engine Modification: Handbrake (Serviceable): Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: Rear Tyre Size: 195/65 R15 195/65 R15

Front Left Side: West Lake 4 mm Rear Left Side: West Lake 4 mm Front Right Side: Rear Right Side: West Lake 4 mm West Lake 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,612.76	175.00	1,437.76	89.15
Miscellaneous Items		0.00	0.00	0.00	
Labour		700.00	600.00	100.00	14.29
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	2,312.76	775.00	1,537.76	66.49
	+ GST 7.00/7.00% (S\$)	161.89	54.25	107.64	66.49

Nett Amount (S\$)	2,474.65	829.25	1,645.40	66.49
+ Loss of Us	se (2.0 x S\$50.00/day) (S\$)	100.00		
+ Car Renta	I (2.0 x S\$125.19/day) (S\$)	250.38		
	+ Doc/Search Fee (S\$)	2.00		
	Nett Liability (S\$)	1,181.63		
G	lobal Sum Settlement (S\$)	1,180.00		

INSPECTION

Date of Assignment: 26/04/2021

ComfortDelGro Engineering Pte Ltd (Loyang) Date Inspected: Inspected At: 27/04/2021

59 Loyang Drive Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: Muhammad Nazril Bin Abdullah Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*FRT DOOR RH	Repair	1,797.20 FL	*- FL
2	1	*FRT DOOR COMFORT LOGO RH	Necessary	75.00 FS	*75.00 FS
3	1	*FRT DOOR ADVERTISEMENT RH	Necessary	100.00 FS	*100.00 FS
F=Fr	nchise part. S=SpcNett. L	=ListItemDisc.			
			Sub Total (S\$)	1,972.20	175.00
			- List Item Discount on L Items 20.00/20.00% (S\$)	359.44	0.00
			Total Parts (S\$)	1,612.76	175.00
			Report was unsubmitted during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No Particulars	Lab.Type	Repairer's	Amount
Labour Items			
1 PANEL BEATING	New	400.00	350.00
2 SPRAY PAINTING CHARGE	New	300.00	250.00
	Gross Labour Cost (S\$)	700.00	600.00
Report was unsubmitted duri	ing this print-out.		

< END OF ESTIMATES >