

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG21005146/KQF3E2

**Date:** 08/07/2021

### REFERENCE

Insured/Claimant: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD Policy No: 0999993650

Date of Loss: 12/04/2021

Nature of Claim: OD

Claim No: 6473742384SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG6355B	Engine No:	65195034218196
Make & Model:	MERCEDES-BENZ VITO 109, 1.6 CDI LONG (M)	Chassis No:	WDF44760323339042
Reg. Date:	18/09/2017 (Man. Year: 2017)	Odometer:	92925 km
Colour:	Red/White		
Engine Capacity:	2143 cc		
Market Value/New Car Price:	S\$70,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/65 R16	Rear Tyre Size:	205/65 R16
Front Left Side:	Royal 9 mm	Rear Left Side:	Royal 9 mm
Front Right Side:	Royal 9 mm	Rear Right Side:	Royal 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,144.65	15,030.15	2,114.50	12.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,480.00	5,940.00	2,540.00	29.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>25,624.65</b>	<b>20,970.15</b>	<b>4,654.50</b>	<b>18.16</b>
<b>- Excess (S\$)</b>	<b>1,900.00</b>	<b>1,900.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>23,724.65</b>	<b>19,070.15</b>	<b>4,654.50</b>	<b>19.62</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,660.73</b>	<b>1,334.91</b>	<b>325.82</b>	<b>19.62</b>
<b>Nett Amount (S\$)</b>	<b>25,385.38</b>	<b>20,405.06</b>	<b>4,980.32</b>	<b>19.62</b>

### INSPECTION

Date of Assignment: 26/04/2021

Date Inspected: 26/04/2021 Inspected At:

Tong Luck Auto Pte Ltd (HQ)  
160 Sin Ming Drive, #07-01 Sin Ming AutoCity  
Singapore 575722

Estimated Period of Repair: 12.0 days

**Adjuster:** KENNETH KONG

**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*REAR WINDSCREEN GLASS</b> (WCP)	Shattered	620.00 F	*620.00 F
2	1		<b>*TAILGATE</b> (WCP)	Bent	1,450.00 F	*1,450.00 F
3	2		<b>*TAILGATE ABSORBER - RH / LH</b> (WCP)	Serviceable	156.00 F	*- F
4	2		<b>*TAILGATE HINGES - RH / LH</b> (WCP)	Repair	230.00 F	*- F
5	1		<b>*TAILGATE LOCK</b> (WCP)	Dented	195.00 F	*195.00 F
6	1		<b>*TAILGATE WEATHERSTRIP</b> (WCP)	Cut	180.00 F	*180.00 F
7	1		<b>*TAILGATE CENTRE TRIM</b> (WCP)	Cracked	28.00 F	*28.00 F
8	5		<b>*TAILGATE CENTRE TRIM RIVETS</b> (WCP)	Necessary	30.25 FS	*20.00 FS
9	1		<b>*TAILGATE INNER HANDLE STRIP</b> (WCP)	Serviceable	28.00 F	*- F
10	1		<b>*TAILGATE INNER TRIMBOARD</b> (WCP)	Cracked	48.00 F	*48.00 F
11	1		<b>*TAILGATE TRIMBOARD CLIPS</b> (15PCS)(WCP)	Necessary	90.75 FS	*50.00 FS
12	1		<b>*TAILGATE CENTRE LOGO</b> (WCP)	Necessary	48.00 F	*48.00 F
13	1		<b>*TAILGATE VITO EMBLEM</b> (WCP)	Necessary	52.00 F	*52.00 F
14	1		<b>*TAILGATE 114 CDI EMBLEM</b> (WCP)	Necessary	62.00 F	*62.00 F
15	1		<b>*TAILGATE C &amp; C EMBLEM</b> (WCP)	Necessary	38.00 F	*38.00 F
16	1		<b>*TAILGATE WIPER MOTOR</b> (WCP)	Mtg Cracked	310.00 F	*310.00 F
17	1		<b>*TAILGATE WIPER MOTOR COVER</b> (WCP)	Serviceable	75.00 F	*- F
18	1		<b>*TAILGATE WIPER BLADE</b> (WCP)	Serviceable	48.00 F	*- F
19	1		<b>*TAILGATE WIPER ARM</b> (WCP)	Serviceable	98.00 F	*- F
20	1		<b>*TAILGATE WIPER CAP</b> (WCP)	Serviceable	12.00 F	*- F
21	1		<b>*REAR END PANEL (OUTER)</b> (WCP)	Bent	252.00 F	*252.00 F
22	1		<b>*REAR END PANEL (INNER)</b> (WCP)	Bent	285.00 F	*285.00 F
23	1		<b>*REAR BUMPER</b> (WCP)	Buckled	980.00 F	*980.00 F
24	1		<b>*REAR BUMPER REINFORCEMENT</b> (WCP)	Cracked / Distorted	135.00 F	*135.00 F
25	2		<b>*REAR BUMPER RETAINER - LH / RH</b> (WCP)	Distorted	130.00 F	*130.00 F
26	1		<b>*REAR BUMPER REFLECTOR - RH / LH</b> (WCP)	N/S Broken	110.00 F	*55.00 F
27	1		<b>*REAR BUMPER SENSOR CABLE</b> (WCP)	Torn	115.00 F	*115.00 F
28	1		<b>*REAR BUMPER REVERSE SENSOR</b> (4PCS)(WCP)	Shorted(3Pcs Only)	540.00 F	*405.00 F
29	4		<b>*REAR BUMPER SENSOR SEALS</b> (WCP)	Necessary	32.00 F	*32.00 F
30	1		<b>*REAR BUMPER CLIPS</b> (15PCS)(WCP)	Necessary	90.75 FS	*50.00 FS
31	2		<b>*TAILLAMP ASSY - RH / LH</b> (WCP)	Cracked	1,100.00 F	*1,100.00 F
32	2		<b>*TAILLAMP ASSY LOWER GARNISH - RH / LH</b> (WCP)	Dented / Distorted	196.00 F	*196.00 F
33	1		<b>*BONNET</b> (WCP)	Repair	850.00 F	*- F

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
34	1		<b>*HEADLAMP ASSY - LH</b> (WCP)	Cracked	1,850.00 F	*1,850.00 F
35	1		<b>*FRONT BUMPER</b> (WCP)	Bent	780.00 F	*780.00 F
36	1		<b>*FRONT BUMPER REINFORCEMENT</b> (WCP)	Bent	480.00 F	*480.00 F
37	1		<b>*FRONT BUMPER CARRIER - LH</b> (WCP)	Cracked	75.00 F	*75.00 F
38	1		<b>*FRONT BUMPER SIDE RETAINER - LH</b> (WCP)	Serviceable	58.00 F	*- F
39	1		<b>*FRONT BUMPER CLIPS</b> (15PCS)(WCP)	Necessary	107.25 FS	*50.00 FS
40	1		<b>*REAR WINDSCREEN SEALANT</b>	Necessary	60.00 FS	*40.00 FS
41	1		<b>*TAILGATE 70KM/H STICKER</b>	Necessary	25.00 FS	*12.00 FS
42	1		<b>*TAILGATE 6 PAX STICKER</b>	Necessary	25.00 FS	*12.00 FS
43	1		<b>*REAR NUMBER PLATE</b>	Dented	40.00 FS	*40.00 FS
44	1		<b>*FRONT NUMBER PLATE</b>	Dented	40.00 FS	*40.00 FS
45	2		<b>*FRONT SAFETY BELT - RH / LH</b> (WCP) (Supplementary)	Jammed	1,178.84 F	*1,178.84 F
46	1		<b>*FRONT SAFETY BELT - CENTRE</b> (WCP) (Supplementary)	Jammed	589.48 F	*589.48 F
47	1		<b>*AIRBAG CONTROL UNIT</b> (WCP) (Supplementary)	Necessary	1,196.00 F	*1,196.00 F
48	1		<b>*REAR END PANEL TOP GARNISH</b> (WCP) (Supplementary)	Dented	98.00 F	*98.00 F
49	1		<b>*TAIL LAMP CORNER PILLAR - LH</b> (WCP) (Supplementary)	Bent	120.00 F	*120.00 F
50	1		<b>*REAR SPARE TYRE HOLDER</b> (WCP) (Supplementary)	Bent	295.00 F	*295.00 F

F=Franchise part. S=SpcNett.

<b>Sub Total (S\$)</b>	<b>15,632.32</b>	<b>13,692.32</b>
<b>+ Margin on L,N Items 10.00/10.00% (S\$)</b>	1,512.33	1,337.83
<b>Total Parts (S\$)</b>	<b>17,144.65</b>	<b>15,030.15</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	150.00	120.00
2	TO TRANSFER DAMAGED TAILGATE INTERIOR MECHANISM TO NEW TAILGATE	New	120.00	60.00
3	TO REMOVE AND REFIT FRONT AND REAR BUMPER SENSOR	New	200.00	120.00
4	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	40.00
5	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS (FRONT & REAR PORTION)	New	1,800.00	1,200.00
6	TO SUPPLY ART WORKS & SPRAY BARCODE ON TAILGATE, RH BODY PANEL AND BONNET	New	3,500.00	2,800.00
7	TO PANEL BEAT AND STRAIGHTEN REAR FLOORBOARD PANEL, FRONT & REAR CHASSIS FRAME, TO CUT AND WELD REAR END PANEL, INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME	New	1,800.00	1,100.00
8	TO REMOVE AND REFIT FRONT SAFETY BELT AND AIRBAG CONTROL UNIT (Supplementary)	New	480.00	250.00
9	TO RESET AND REPROGRAMME AIRBAG MODULE (Supplementary)	New	350.00	250.00
<b>Gross Labour Cost (\$)</b>			<b>8,480.00</b>	<b>5,940.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >