

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21005147/KPS3Q2
Date: 13/08/2021**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Claimant Vehicle No : SML46B

Date of Loss: 22/04/2021

Policy No:

Insured Vehicle No :

Nature of Claim:

SMN2744X

TP

Claim No: 9262921117SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SML46B**
Make & Model: TOYOTA VELLFIRE, 2.5 CVT (A)
Reg. Date: 07/01/2019 (Man. Year: 2018)
Colour: Metallic Black
Engine Capacity: 2493 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**Engine No: 2ARJ176908
Chassis No: AGH300212320
Odometer: 177957 km**CONDITION OF VEHICLE AT THE TIME OF SURVEY**General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:**CONDITION OF TYRES**Front Tyre Size: 235/50 R18 Rear Tyre Size: 235/50 R18
Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 6 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,149.26	2,176.11	973.15	30.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,300.00	520.00	780.00	60.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,449.26	2,696.11	1,753.15	39.40
Approved Total (Overridden) (S\$)		2,150.00		

(S\$)	4,449.26	2,150.00	2,299.26	51.68
+ GST 7.00/7.00% (S\$)	311.45	150.50	160.95	51.68
Nett Amount (S\$)	4,760.71	2,300.50	2,460.21	51.68
+ Loss of Use (2.0 x S\$120.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,547.95		
Global Sum Settlement (S\$)		2,540.00		

INSPECTION

Date of Assignment: 26/04/2021

Date Inspected: 27/04/2021

Estimated Period of Repair: 2.0 days

 Inspected At: Hui Yang Motor Pte Ltd (HQ)
 176 Sin Ming Drive #04-02, Sin Ming AutoCare
 Singapore 575721
Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	1,812.50 FL	*1,614.00 FL
2	1		*FRONT BUMPER CENTRE CHROME	Warped	281.58 FL	*281.58 FL
3	1		*FRONT BUMPER LOWER GRILLE	Distorted	274.45 FL	*274.45 FL
4	1		*FRONT BUMPER LOWER LH COVER	Serviceable	121.50 FL	*- FL
5	1		*FRONT BUMPER SPONGE	Cracked	171.45 FL	*171.45 FL
6	1		*FRONT BUMPER REINFORCEMENT	Repair	358.50 FL	*- FL
7	1		*FRONT FCENTRE GRILLE BASE	Cracked	481.50 FL	*311.20 FL
8	1		*FRONT FCENTRE GRILLE LOWER GARNISH	Cracked	280.50 FL	*208.80 FL
9	2		*FRONT HEADLAMP LOWER BRACKET	Serviceable	363.70 FL	*- FL
10	1		*FRONT NUMBER PLATE	Necessary	40.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,185.68	2,891.48
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,036.42	715.37
Total Parts (\$\$)	3,149.26	2,176.11

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	WIRING	New	100.00	20.00
2	SPRAY PAINTING	New	600.00	250.00
3	LABOUR CHARGES	New	600.00	250.00
Gross Labour Cost (\$\$)			1,300.00	520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >