



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. EU 1882U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	TAILGATE GLASS INNER SEAL (CONSISTENT)	NECESSARY	196.00	196.00
1	TAILGATE (CONSISTENT)	DISTORTED	1,812.00	1,812.00
1	TAILGATE OUTER GARNISH (CONSISTENT)	NOT NECESSARY	455.00	-
1	TAILGATE ESQUIRE EMBLEM (CONSISTENT)	NECESSARY	92.50	92.50
1	HYBRID EMBLEM (CONSISTENT)	NECESSARY	78.00	78.00
1	TAILGATE INNER LOCK (CONSISTENT)	NOT NECESSARY	470.00	-
1	TAILGATE INNER BOARD (CONSISTENT)	CRACKED	570.00	570.00
1	TAILGATE WEATHERSTRIP (CONSISTENT)	NOT NECESSARY	277.00	-
1	BUMPER REAR (CONSISTENT)	DEFORMED	989.00	989.00
2	BUMPER SIDE BRACKET REAR @\$122.00 (CONSISTENT)	NOT NECESSARY	244.00	-
1	END PANEL REAR (CONSISTENT)	DENTED	985.00	683.50
1	END PANEL TOP GARNISH REAR (CONSISTENT)	DEFORMED	155.00	155.00
1	REMOTE ANTENNA (CONSISTENT)	CRACKED	185.00	185.00
1	TOOL TOP GARNISH (CONSISTENT)	DEFORMED	487.00	487.00
1	EXHAUST BOX REAR (CONSISTENT)	NOT NECESSARY	408.00	-
2	FENDER SIDE GARNISH REAR @\$385.00(CONSISTENT)	NOT NECESSARY	770.00	-
	LESS 25% DISCOUNT		-2,043.38	-1,312.00
			6,130.12	3,936.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REVERSE CAMERA (SN)(CONSISTENT)	NOT NECESSARY	480.00	-
2	REVERSE SENSOR @\$490.00 (SN)(CONSISTENT)	DAMAGED	980.00	200.00
1	WINDSCREEN GUM (SN)(CONSISTENT)	NECESSARY	40.00	40.00
2	BUMPER REFLECTOR MOULDING REAR @\$95.00 (SN)(CONSISTENT)	NECESSARY	190.00	150.00
1	NUMBER PLATE AND BASE REAR (SN)(CONSISTENT)	NOT NECESSARY	50.00	-
			1,740.00	390.00
<b><u>LABOUR</u></b>				
	REMOVE & REPLACE ACCIDENT DAMAGED PARTS.		1,200.00	800.00
	SPRAY PAINTING ACCIDENT AFFECTED PARTS.		900.00	800.00
	REMOVE AND REFIX WINDSCREEN REAR.		120.00	120.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND REFIT REAR UPHOLSTERY ,CARPET AND ETC.	NOT NECESSARY	180.00	80.00
	REMOVE & REFIX REAR EXHAUST PIPE.		50.00	-
	CHECK REAR WIRING AND LIGHTING OPERATION.		90.00	30.00
	UNDERCOAT.		120.00	60.00
			2,660.00	1,890.00
<b>GRAND TOTAL</b>			<b>10,530.12</b>	<b>6,216.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>6,216.00</b>

Report Ref No. CC4/ASM21005155/Aga3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.