

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21005160/ARA3Q2
Date: 12/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SLB1738X	Insured Vehicle No :	SMM7313D
Date of Loss:	20/04/2021	Nature of Claim:	TP
		Claim No:	5352059421SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB1738X		
Make & Model:	MERCEDES-BENZ E200, 2.0 SEDAN EDITION E (R18 LED SR) (A)	Engine No:	27492030538837
Reg. Date:	30/03/2016 (Man. Year: 2015)	Chassis No:	WDD2120342B277601
Colour:	Silver	Odometer:	92304 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,185.00	3,270.60	2,914.40	47.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	830.00	870.00	51.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,885.00	4,100.60	3,784.40	47.99
Approved Total (Overridden) (S\$)		3,250.00		

(S\$)	7,885.00	3,250.00	4,635.00	58.78
+ GST 7.00/7.00% (S\$)	551.95	227.50	324.45	58.78
Nett Amount (S\$)	8,436.95	3,477.50	4,959.45	58.78
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
(S\$)		3,877.50		
Liabe Amount (50.00%) (S\$)		1,938.75		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,940.75		

INSPECTION

Date of Assignment: 26/04/2021

Date Inspected: 26/04/2021

Inspected At: Success United Pte Ltd (HQ)
2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub
Singapore 417921

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT DOOR LH	Dented	2,830.00 F	*2,145.00 FL
2	1		*FRT DOOR WEATHERSTRIP LH	Necessary	420.00 F	*280.00 FL
3	1		*FRT DOOR WING MIRROR ASSY (WITH MOTOR)	Damaged	1,850.00 F	*914.00 FL
4	1		*FRT DOOR WING MIRROR COVER LH	Repair	450.00 F	*- FL
5	1		*FRT DOOR WING MIRROR BLINKER LAMP LH	Not Necessary	185.00 F	*- FL
6	1		*FRT DOOR MIRROR GLASS LH	Cracked	450.00 F	*295.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	6,185.00	3,634.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	363.40
Total Parts (\$)	6,185.00	3,270.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REPLACE & TRANSFER DOOR COMPONENTS	New	200.00	80.00
2	TO REMOVE ,REPAIR AND REPLACED DAMAGED BODYPARTS ,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT	New	700.00	400.00
3	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA	New	800.00	350.00
Gross Labour Cost (S\$)			1,700.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >