

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Page No.:1 of 1

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD CS3/ASM21005164/Uvce2 Ref: 8 SHENTON WAY #24-01 AXA Date: 11/05/2021 **TOWERSINGAPORE 068811** ATTN: YU DOMINIC YISHAN Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SHA 2826X GZ 609A Veh. Inspected Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S1M03770 Excess (\$) 0.00 YU DOMINIC YISHAN **Assign Date** 27/04/2021 Assign From **Vehicle Particulars & Condition** 2. TOYOTA HIACE (M) Make & Model 2986 c.c HIDDEN 2003 Engine No. Year of Reg. LH1621008702 WHITE Chassis No. Colour 599245 KM Odometer Steering **IN ORDER IN ORDER** NIL **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 185 R14 **CST TIRES** 6 mm **CST TIRES** L/H Front Tyre 185 R14 6 mm 185 R14 **CST TIRES** R/H Rear Tyre 6 mm **CST TIRES** L/H Rear Tyre 185 R14 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. 5. **General Information** 03/04/2021 06/05/2021 ( 10:32 AM ) Inspect Date / Time Accident Date KIM SENG TECK MOTOR WORKS Survey held at BLK 3021A UBI ROAD 1 #01-42 SINGAPORE 408715 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$800-\$1,000 5b. **Estimate Days of Repair** 

Report Ref No. CS3/ASM21005164/Uvce2

Inspected By

**ESTIMATED NORMAL PERIOD FOR REPAIR:** 

CHUA KANG SENG

K.K.LAU CPT(RET)

Licensed Appraiser BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

1 Working Days