

SMQ39BC.

Honda Shuttle

TP chim
reize.

GK82100758

Front Bumper	Distorted	1050.50 ✓
Front Bumper Clips.	New	30 (SN) ✓
Front Bumper Side Holder LH.	Dented	35 ✓
Front Bumper Sensor	Dented	280 (SN) ✓
Front Bumper Side Grille.	HP m	65.80 ✗
Front Bumper Reinforcement	Dented	420.90 ✓
Front Bumper lower Grille.	HP m	216 ✗
Front Grille	Crushed	363.30 ✓
Front Grille Chrome Moulding.	HP m	292.60 ✗
Front Grille Clips.	HP m	20 (SN) ✓
Front Grille Logo	HP m	48.20 ✓
Headlamp LH	Crushed	2128.70 ✓
Headlamp lower Bracket LH.	Crushed	48. ✓

SMQ3913C

Front LH Fender	Buckled torn	489.90 ✓
Front LH Fender Inner Shield		178.20 ✓
Front LH Fender Inner Shield Caps.	in	30(SN) ✓
Front LH Fender Lower Panel.	Buckled	589.10 ✓
Air Resonator Box.	Crushed	120.40 ✓
Front LH Wheel Rim.	XCP in	300(SN) +
Front LH Wheel Rim Cover	cut	80(SN) ✓
Front LH Tyre.	be in	250(SN) +
Front LH Shock Absorber	XCP in	306.90 +
Front LH Lower Arm.	Best	321.80 ✓
Front LH Knuckle Arm.	Dmgd	363.40 ✓
Front LH Wheel Hub c/w Bearing.	Dmgd	206.90 ✓
Front LH Anti-Roll Bar Linkage	XCP in	89.60 +
Sleeping Rack and Pinion	XCP in	1550.60 +

SMQ3913C.

Panel Beating.

Spray Painting.

Wiring.

To remove front bumper sensor

To spray left coat.

To remove front undercarriage.

To perform wheel alignment.

~~1400~~ 800

~~1200~~ 600

~~1000~~ 300

~~1000~~ 500

~~1500~~ 400

~~3500~~ 1800

~~1500~~ 800

Wkst: 6359.30 Labour: 1780

km 20%: 5087.44 Total: 7227.44

S-N: 360

H/s: S.T.K. ✓

06 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: