



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD
73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556
ATTN: CHARLOTTE

Ref: CS/INC21005175/Uqf3n2

Date: 12/05/2021

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PD 1033M	Veh. Inspected	PC 7027Y
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1129464-002	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	27/04/2021

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE COMMUTER (A)	c.c	2754
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	GDH2232000125	Colour	WHITE
Odometer	175884 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	MICHELIN	6 mm
L/H Front Tyre	195 R15	MICHELIN	6 mm
R/H Rear Tyre	195 R15	MICHELIN	6 mm
L/H Rear Tyre	195 R15	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/04/2021	Inspect Date / Time	27/04/2021 (10:11 AM)
Survey held at	15 KAKI BUKI ROAD 4, #01-05/53		
Repairer	ASIA MOTORSPORTS SOLUTION PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days