



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBJ 4846Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HANDLE GUARD / ALUM / BLACK	CUT	358.00	358.00
1	SET BRAKE LEVER & CLUTCH LEVER	CUT	76.00	76.00
1	MIRROR (R)	CUT	39.00	39.00
1	FRONT FENDER	CUT	102.00	102.00
1	CRASH BAR / ORANGE	CUT	433.00	433.00
1	REAR SIGNAL / REAR (R)	BROKEN	65.00	65.00
1	REAR BOX	CUT	688.00	688.00
1	FOOTREST BRACKET / REAR / (R)	BENT	84.00	84.00
1	FOOTREST PIN / REAR / (R)	MISSING	11.00	11.00
1	FOOTREST LOCK PIN	MISSING	2.00	2.00
1	LOCK PLATE 1	MISSING	6.00	6.00
1	LOCK PLATE 2	MISSING	6.00	6.00
1	REAR WHEEL AXLE	CUT	62.00	62.00
1	REAR AXLE NUT	CUT	7.00	7.00
1	REAR ADJUSTER BLACK	NOT NECESSARY	11.00	-
1	FOOTREST / REAR / (R)	MISSING	34.00	34.00
	LESS 10% DISCOUNT		-	-197.30
			1,984.00	1,775.70
	<u>LABOUR</u>			
	LABOUR.		280.00	200.00
	TOWING.	NOT NECESSARY	45.00	-
			325.00	200.00
	GRAND TOTAL		2,309.00	1,975.70
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			1,975.70

Report Ref No. CS/INC21005179/Gqf3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.